Remington Arms Co., Inc. Product Service Legal Case #:7360

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 256822 2/1/2012 2/2/2012 X

Customer Information

Business First Name Last Name Street City State Zip Age Contact Type H n/a 10487 Valencia Rd. FL33772 Incident John Mellny Seminole E jmelny@aol.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern

Concern:1008 Fired on Bolt Closing

Unknown

С

S FBC

SR# 10254 - When closing bolt the gun fired. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 710/3006 SPRG
 27410
 71197100
 RY
 11/20/2004 6:03:53 AM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART DC 6003R-REGULAR SCOPE BASE U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date Settlement APV APV

Per Ilion - Check over, clean, test fire @ n/c

Repair/Replacement
Cost
Date

\$27

2/9/12: Per Ilion - Could not duplicate concern. To restore confidence in rifle, will check over completely, clean, safety check & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date .		2/2/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		RY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7360&Type=Case

2/17/2012

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn, Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Service Request

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLFASE RETAIN THIS YOUR RECORDS.

Service Request Number a Description SR00010254

71197100 Model 710

Customer: JOHN MELLNY 10487 VALENCIA RD SEMINOLE, FL 33772 US

Email: jmellny@aol.com

Date of Request 01/19/2012 Printed)1/19/2012

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep. returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return M994 - GUN FIRED

Service Request Section when closing the bolt the gun fired

Parts And Service Details

Type Material

Description

Qty Needed

Price Disc Amount

RE00256822

could not dyphoste concern.

To restore confidence in rifle

will check over completely, clear,

safety check + test Rim At N/E

Sub Total:

#230145

Est Sales Tax:

.00 .00

Grand Total:

\$.00





