Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8174

_	- ^	
Case	Inform	ation

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 293165 12/14/2012 11/16/2012 11/12/2012

Customer Information

Business First Name Last Name City State Zip Contact Type Street Age Incident Frederick Etcheverry 5507 S.E. 32nd Des Moines 50320 C 515-661-3717

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Shot hole in wall and couch

Cause: 4038 Could Not Duplicate Concern Concern: 1020 Fired on Bolt Opening

Unknown

S

11/16/12 Per call from Frederick, on Monday he bought a new 770 from Bass Pro and had loaded it and was working the action. He remembered he had one round still in the magazine and was going to unload it and when opening the bolt it fired. The safety was on and his finger was not on the trigger. It put a hole in his wall and couch.cm 1/4 Etcheverry said he did not disassemble the firing pin. If it came from the factory disassembled that we should cover damages.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type 770/300 WIN MA M71868661 DG 9/26/2012 11:23:42 AM Remington CF/BA 85648 Date Purchased Where Purchased Accessories Original Owner

AMERICAN ROD & GUN SCOPE, RINGS, BASE

Y

CONCERN: FBO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Repair/Replacement Cost Repair/Replacement Date

11/16/12 Mailing ARS.cm 1/4/13 Called Etcheverry to let him know we could not duplicate issue after reassembling the firing pin and would not cover property damage.cm 1/7 Emailed Ilion to check tamper evident seals are in place and add that to the pictures.cm 1/11/13 Spoke with D. Watkins, ok'd covering cost of repairs. Called Etcheverry and he will send quote for car repair and couch. I already have wall repair receipt. We will assemble and test the 770. Will send release to be signed.cm

Examination[Remington/CF/BA]


Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/17/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	REASSM THE FIR PIN FOR EXAMINATION
Barrel	Description		24" 300 WIN MAG
	Date Code]	DG
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed	7	


http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8174&Type=Case

1/11/2013

PrintDisplay Page 2 of 2

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt Face Hand	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Worn; Functioning	HEADED WITH X-MAX PLUGS ONLY
	Notch Condition	Select	
\/:	Condition	Select	
Magazine	Box Condition	Like new; Functioning	
	Exterior Condition	Like new; Functioning	REC'D WITH FIR PIN UNASSM NO DAMAGE TO FIR PIN
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
B	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	10313	False	
Trigger	Condition	Like new; Functioning	·
	Pull	Select	5#
	Altered	False	SEALANT NOT PRESENT
	Sub-Assembly	Other Remington	





PS 26592

24" 069/12

8174

November 16, 2012

Frederick Etcheverry 5507 S.E. 32nd St Des Moines, IA 50320

Subject: Case # 8174, Model 770, SR # 35266

Dear Mr. Etcheverry,


I am sorry to hear of the problems you had with the Remington firearm. Please include a copy of this letter with the rifle as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the product is logged in correctly.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com





Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com November 29, 2012 - Mailed 12/11/12

Remington Arms Company, LLC Consumer Affairs Administrator 870 Remington Drive PO Box 700 Madison, NC 27025

Re:

Frederic Etcheverry

Case #8174, Model 770, SR#35266

Dear Ms. Mitchell,

Thank you for your response regarding the firearm I purchased. I have included the information you requested with the firearm, as well as, the following:

- Pictures of the property damage sustained as a result of the defective firearm
- Invoice for a portion of the repair to the damage sustained as a result of the defective
- Original receipt for purchase of the defective firearm
- Written statement from Frederic Etcheverry regarding defective firearm

Please contact us after review of this information to discuss how you plan to resolve the damage sustained as a result of this defective firearm and reimbursement for the defective firearm. Damage to the walls in the Frederic and Melissa Etcheverry residence, Frederic Etcheverry's vehicle damage, and the couch at the Linda Collicott residence have not yet been repaired. Repair was made to the dry wall and outside wall of the Linda Collicott home, along with the south outside wall of the Frederic and Melissa Etcheverry home.

We appreciate your prompt attention to this request and would like a response within 30 days of the date of this letter.

Sincerely.

Frederic and Melissa Etcheverry

5507 SE 32nd Street Des Moines, IA 50320

515-897-8885

the

product demonstrations Shops Altoona on FACEBOOK! Pro Bass

770 Pkg Bpe P Wtail Pro 7 1401599

043

Sales Person: Nick

Outdoor Rewards Number: ****6538 Total Points Earned: Balance: \$18.

Subtotal

66

370

AMEX (****04/REF:200389)

November 29, 2012

On Monday November 12, 2012, I purchased a rifle at Bass Pro Shop in Altoona, Iowa. This is a Remington Rifle Model WTail Pro 770 for the price of \$349.99 + tax for a total of \$370.99. (see attached receipt) When I came back home, I decided to open the box and examine my new rifle. I installed the bolt on the rifle, then read the owner's manual and got familiar with the safety system and safety procedures recommended by Remington for this type of firearm. I loaded 3 cartridges into the magazine in order to verify that the magazine was okay. Next, I unloaded the magazine. Before I realized I had left one cartridge in the magazine, I inserted the magazine into the rifle. I checked and made sure that the safety was on and tried to remove the magazine. I could not remove the magazine so decided to load the chamber and eject the cartridge from the chamber by opening the bolt and pulling it fully rearward twice, in order to load and eject the cartridge. At this time the safety was on. When I opened the bolt the second time the rifle discharged accidentally. I'm 100 % sure that the safety was on because I checked that at each phase of the process. My finger was not on the trigger. My right hand was busy with the bolt and I was holding the stock with my left hand. The rifle discharged and created damage to our home and our neighbor's home. We are all very thankful no one was in line with the bullet and that we only sustained property damage as a result of the defective gun.

The bullet passed through the wall in our living room and into the garage. While passing through the garage, the paint and rear glass on my vehicle got damaged. Then the bullet passed through the external wall of the garage of my home and through the external wall then internal wall of my neighbor's home, only to be stopped by a couch. Please see attached photos of damage sustained. I'm persuaded that this incident should not happen at any time and a rifle with a safety "On" should not fire at any time.

I would like to add that I'm familiar with and have over 25 years' experience with the use of firearms of many types. I've been hunting for many years and have been trained with regard to the use of firearms in the military.

Sincerely,

Frederic Etcheverry

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Prod Serv #8174

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description Date of Request: 11/16/2012 Date Printed: 11/16/2012 SR00035266 M71868661 Model 770 RIFLE Caliber: 300 Destination: Arms Services Customer: FREDERICK ETCHEVERRY 14 Hoefler Ave 5507 S.E. 32ND ST DES MOINES, LA 50320 US Ilion, NY 13357 US Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Prod Serv #8174 Parts And Service Details. Description Material Qty Warranty Disc Type Needed THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) Sub Total: .00 being sent based on the conversation with our representative. Est Sales Tax: .00


\$.00

Grand Total:

NOTE: Please complete and print this form, and then include it with your firearm.


Model Number: 170	[202//
Model Number: 1710	Serial Number: 35266
Are you the original owner?: YES NO	
Name: Freden = Etzhevezny	Date of Purchase: 11/12/12
Address (no PO Boxes): SSM SE 32	ind street
city: Des Moines	state: TA Zip: 50320
Phone (Daytime): 515-	Fex:
E-mail Address:(if e-mail address is provided, notification sent)	of receipt and shipment will be
E-mail Address:	
I would like to receive future e-mail updates from Rer	mington.
Please describe your problem and date of occurrence	;
See attached letters	+ documentation
The state of the s	:
The Control of the Co	
The second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second section is a section in the section in the section is a section in the section in the section is a section in the section in the section is a section in the section in the section is a section in the section in the section in the section is a section in the section	į
THE PROPERTY.	<u> </u>
500 characters left	A CONTRACTOR OF THE CONTRACTOR
Ammunition Information:	
Manufaciurer:	Тура:
Other (i.e. bullet weight/type, shot size, powder):	
·	·
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:


Frederic Etcheverry residence-initial bullet hole



Frederic Etcheverry residence—other side of initial bullet hole-passed into garage.
North
Wall


(12) Linda Collicott residence-wall behind couch after repair






(M-Same as #3 - scrapes in glass









Trederic Etcheverry garage - Southwall- passed through here offer passing over runstang





Then across to neighbors hime. (10) North wall of Linda Collicett residence




(1) Repaired North inside wall of Linda Collicott residence


- See invoice we did not take a picture before repair 13) Back of couch-linda Collient-Sitting up against wall on rivith side of house



(14) Cushim un couch - bullet broke sipper as well



TS Note multiple holes in couch where bulletended up



ARS LABEL REQUEST FORM

DATE: 11/16/2012	CD000250//
DATE: 11/16/2012	Service Request # SR00035266
QUANTITY: 1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY: mitchellcs	email address:
Dueineen	
Business:	Remington Service PO Box 700
	Madison, NC 27025-0700 www.remington.com
	www.remington.com
	LABEL INFORMATION
MAIL LABEL TO:	FREDERICK ETCHEVERRY
	5507 S.E. 32ND ST DES MOINES, IA 50320 US
	SR00035266
	Email:
RETURN ITEM TO:	ILN
	Arms Services
	45VEGS NOV 16 2012 ACT WT 10.0 LBS #PK 1
	AND CARCOM
	TRACKING# 124XX5969067896401 ALL CURRENCY USD REF 1:SR00035286 REF 2:
	UC D CD CNS 0.00 FRT: 3RD
	SHIPMENT PUB RATE CHARGES: SVC 177 050
	DC 0.00 DGD U.UU BB 0.00 BOD 0.00
	TOT PUB CHG 10.31 PUB+HANDLING 10.31

ATTN: Prod Serv #8174

PS 26606





