

Remington Arms Co., Inc.
Product Service
Legal Case #:7312

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255531	1/20/2012	1/23/2012	1/23/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Beikirch's		Beikirch's	POB 151 930 Linden Ave	East Rochester	NY	14445		W 585-248-3660

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S Fired when closing bolt	Concern:1008 Fired on Bolt Closing			
C				

2/8/12 Per note with rifle, this gun goes off when you close the action.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/223 REM	25798	B6431294	BD	1/1/1983
Date Purchased	Where Purchased	Accessories	Original Owner			
	J F KUHNS LBR CO ERIE PA	SCOPE BASE,SLING	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement


Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, can offer to replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	23.01	2/8/2012				

2/8/12 Per note with rifle, trigger assm dirty, trigger not returning under sear. Can offer to replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/23/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	TRIG HAS NO RETURN WITH PULL SETTING BELOW SPECS
Barrel	Description		24" 223 REM
	Date Code		BD
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR WILL FOLLOW DOWN
	Pull	---Select---	I#
	Altered	False	40X TPA
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,SLING



Customer Acc't#: _____

Customer Phone#: _____

Customer Cell#: _____

Customer Fax#: _____

Customer Email: _____

AMOUNT

Discipline

1-585-327-5057.

RECEIVED
JAN 24 2012

BY: _____

Model: 700



T.A. dirty, Temp. not returning
under seal. Can often to
replace TPA, clean & test fine
~~ATOP~~ under BCP for 8 to 10.

Quote:

PLEASE Pay from this Invoice - NO BILL TO FOLLOW!

www.Beikirchs.com

PS 26931

