

Remington Arms Co., Inc.
Product Service
Legal Case #:7701

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
269905	5/31/2012	6/1/2012	6/1/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Jim	Curcuruto	515 Berkshire Rd.	Southbury	CT	06488		H 203-610-9909

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FBC	Concern:1020 Fired on Bolt Opening			
C				

Customer sent rifle in w/note. Customer stated the rifle belongs to his father and his father had an accidental discharge years ago - FBC & he shot the couch of their hunting cabin. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6414698	LO	2/9/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	ROSKIN BROS MIDDLETOWN NY	BOTTOM HALF SEE THRU RINGS	N			

CONCERN:ACCIDENTAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

6/8/12: Per Ilion - Could not duplicate concern. TA dirty & rusty. Replace TA, clean & test fire under BLM - quote. Customer called on 6/1 & spoke to CSR. He approved & paid for quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/1/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		LO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, RUSTY
	Pull	--Select--	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF SEE THRU RINGS



NATIONAL SHOOTING SPORTS FOUNDATION, INC.

11 Mile Hill Road • Newtown, CT 06470-2359 • Tel (203) 426-1320 • Fax (203) 426-1087 • www.nssf.org

22"
LOZ/77
S.S.#
006

7701

5/29/12

Remington Firearms
Attn: Bruce Travis, Product Service
14 Hoefler Avenue
Ilion, NY 13357

Hello Bruce,

Thank you for the factory tour on May 22nd. I enjoyed learning about the production process there at Remington and was impressed with the size of your operation.

Enclosed is the Model 700 that we discussed. It was purchased new by my father in about 1975 and he had an accidental discharge a number of years back while unloading the firearm. As with this model, he took the safety off to unload and went to pull the bolt back to unload and the firearm went off resulting in shooting the couch of our hunting cabin in Fulton County NY.

You mentioned I should send it to your attention for you to take a look at. Please let me know what you find out. I've enclosed a check for \$20, should you require additional payment, please let me know.

Should need any additional information, please contact me.

Thank you,

Jim Curcuruto
515 Berkshire Rd
Southbury CT 06488
203-610-9909

Serial
Number:

A6414698

Model: 700



RE00269905

could not duplicate concern.
T.R. dirty + rusty. Repace TPA,
clean + test under BLP for
\$20 +

Quote **RECEIVED**
JUN 08 2012

BY:

PROMOTE

PROTECT

PRESERVE









