Remington Arms Co., Inc. Product Service Legal Case #:7959

Case Information

RE# Date Opened Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 284269 10/3/2012 9/21/2012 10/4/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact 134 Francis St. C 304-415-5023 Incident Bermie Drennen Jr. Dunbar 25064

Incident Information

Claims Codes Repair Est. **Medical Treatment** Medical Status

ΡI

PD Cause: 4015 Improper Maintenance

Unknown S FBC Concern:1008 Fired on Bolt Closing

C

9/21/12: Customer called in. He stated he had FBC with gun in fall of 1992. He said he inherited the gun from his dad. df

Firearm Information

Model/Ga. SKU DOM Mfg. Serial Bbl. Type 700/7MM REM MA n/a A6453643 KO 5/9/1977 CF/BA Remington

Where Purchased Original Owner **Date Purchased** Accessories

J C PENNY STATESVILLE NC Ν

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement APV Settlement - APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Cost Repair/Replacement Date

9/21/12: Sending a box, ARS & forms from Madison office. df 10/5/12: Per Ilion - TA has dried & sticky lube residue causing parts to bind & work sluggish. Replace TA, clean & test fire under BLM - quote. df 10/18/12: Customer apprvd quote & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code		Comment
Examination	Examiner		B.TRAVIS	
	Exam Date		10/4/2012	
	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	•
Cause	4015	Improper Maintenance		
Barrel	Description		24" 7MM REM MAG	
	Date Code		KO	
	Bore Plugged	False		
	Bulged	False		
	Fired	False		
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		

	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.005
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	Falsc	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY PARTS BIND AND WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	7.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

7959

COPY

September 24, 2012

Bermie Drennen 134 Francis St. Dunbar, WV 25064 Phone: 304-415-5023

Ref: #7959, Model 700, Serial # A6453643

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination, a form and service request.

Please include a copy of this <u>letter</u>, form, and service request to put inside the shipping container. The letter, form and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope that this action will keep you a loyal Bushmaster customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC, Bushmaster Firearms
Phone: 1-800-883-6229 press 0 and ask for ext 8686

Fax: 336-548-7872



T.A. has admed totickylube used a content sing parts to bind a work sing parts to bind a work sing qual. Hope ma TPA, chart por when BCP for & 20. f

[CT 0 5 2012]

BY:

Service Request

Remington Service

Date of Request:

09/24/2012

Printed: 09/24/2012

Madison, NC 27025-0700

ATTN: Product Service

Date

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description

SR00029860

A6453643

Model 700 Center Fire

Customer:

BERMIE DRENNEN 134 FRANCIS ST. DUNBAR, WV 25064 US Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 7959

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

521 Yan

ce Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

Model Number: 760	Serial Number: <i>Alo45</i>		
Are you the original owner?: ☐ YES 🖾 NO			
Name: BERMIE E DRENNEN, JR	Date of Purchase:		
Address (no PO Boxes):			
134 FILANCIS ST.			
City: DUNBAR	City: DUNGAR State: WE Zip: 25064		
Phone (Daytime): 304-415-5023	Fax:		
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be			
sent)			
E-mail Addr □ I would like to receive future e-ma		ngton.	
Please describe your problem a	and date of occurren	ce:	
FALL OF 1992.			
WHEN I CHAMBERED DOWN BOLT, GUN WEN ON GUN WAS PUT AWAY IN CHEEN SHOT SWEET	off. SAFEN	i was	
500 charact	ers left	<u> </u>	
Ammunition Information:			
Manufacturer: WINCHESTER Type: SUPREME			
Other (i.e. bullet weight/type, shot size, powder): I GO GR. FAIL SAFE			
	 		
Handload Information:			
Powder Used: Powder Weight:			
Case/Hull Used: Primer Used:			
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleaning and Lubrication):			

General Repair Form Page 2 of 3

Brand of cleaning solution used: REGULAR GUN OIL?		
How often do you clean the bore? (Months or Number of rounds) <u>NoT SINCE 92</u>		
How often do you clean the action? (Months or Number of rounds) NOT SINCE 92		
How often do you clean the trigger assembly? (Months or Number of rounds) NOT SINCE 92		
Brand of lubricant used: K-MAPT BRAND		
How often do you lubricate the bore? (Months or Number of rounds) NOT SINCE 92		
How often do you lubricate the action? (Months or Number of rounds) NOT SINCE 92		
How often do you lubricate the trigger assembly? (Months or Number of rounds) NOT SINCE 92		
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ☐ YES ☑ NO		
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)		
What were the services		
performed?) Ship your INSURED firearm by either UPS or Parcel Post to:		
Ship your insored health by either ors of Farcer Fost to.		
- AT		
· 		
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.		
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage.		

:: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Reset

ARS LABEL REQUEST FORM

DATE:	09/24/2012	Service Request#	SR00029860	١
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	1
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL	
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com]

LABEL INFORMATION

MAIL LABEL TO:	BERMIE DRENNEN 134 FRANCIS ST. DUNBAR, WV 25064 US SR00029860
	Email:
RETURN ITEM TO:	ILN
	Arms Services
1	

4XX596 SEP 24, 2012 ACT WT 10.0 LBS #PK 1
SVC GNDCOM BL WT 10.0 LBS #PK 1
TRACKING# 1Z4XX5969065526573 ALL CURRENCY USD
REF 1:SR00029860
REF 2:
HC 0.00 CNS 0.00 FRT: 3RD
SHIPMENT PUB RATE CHARGES: SVC T/P USD
DC 0.00 DGD 0.00 RS 0.50
DC 0.00 DGD 0.00
AH 0.00 PR 0.00 ROD 0.00
TOT PUB CHG 9.61 PUB+HANDLING 9.61

ATTN: Product Service

#Pitney Bowes



ShipRequest™



Ship To:

Bermie Drennen

Company:

Address 1:

134 Francis St.

Address 2: Address 3:

City:

Dunbar

State/Province:

West Virginia

ZIP/Postal Code:

25064

Country:

United States

email:

Phone:

Account:

230145

Package Type:

Package

Address Type:

Residential

Deliver By:

Thu, September 27, 2012

Package ID:

8852

Special Instructions:

Sender Name:

Dell Marie Fulcher

email:

dell.fulcher@remington.com

Prepared By:

Dell Fulcher

Phone:

336-548-8686







