PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:7335

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 258670
 2/15/2012
 1/27/2012
 2/16/2012
 1/26/2012
 1/26/2012

Customer Information

Business First Name Last Name Street Type City State Zip Contact Box 187 212 N. 4th H 406-284-6581 Incident Edward 59741 Fonk Manhattan MT

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4006 Altered Adjustments or Components
S FSR Concern:1007 Fired on Safe Release

Unknown

S FSR

1/27/12: Customer called in. He stated he had FSR w/rifle on 1/26/12. No damage, No injury reported. df

Firearm Information

Mfg. Model/Ga. SKU Type Serial ВЫ. DOM CF/BA n/a Remington 700/17 REM A6259569 BI 1/19/1976 **Date Purchased** Where Purchased Original Owner Accessories

MALLCO DIST PHOENIX AZ N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date

APV APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost Date

\$29

1/27/12: Mailing ARS & forms. Box order# 1301678. df 2/20/12: Per Ilion - TA set screws altered. Trigger will not return properly. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
!	Examiner		B.TRAVIS
	Exam Date]	2/16/2012
	Product Type]	RF
	Action Type]	A
	Assigned To]	T.NAGLE
Cause	4006	Altered Adjustments or Components	(BBL IS NOT PART OF RECALL)
	Description		24" 17 REM
	Date Code		BI
	Bore Plugged	False	
1	Bulged	False]
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
			วี

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7335&Type=Case

2/27/2012

Bolt	Firing Pin	Slightly Worn; Functioning	·
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	·
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
RECEIVEI	Bulged	False	
Safety Sear	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	·
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6212	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Remington

BI1/76 1.5#

7335

January 27, 2012

Edward Fonk Box 187 212 N. 4th Manhattan, MT 59741 Phone: 406-284-6581

Ref: #7335, Model 700, Serial # A6259569

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.


Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

A6259569 Model: 700 T.A. Set SCREW'S Altered-Tring. WILL NOT RETURN PROPERLY, Replace TOA, CLEAN + TOST UNDER BLD for 10 20 +



Quole

BY:____

Remington Arms Company, LLC ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com

Service Request

Material

Type

Description

Remington Service

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description Date of Request: 01/27/2012 SR00011165 A6259569 Date Printed: 01/27/2012 Model 700 Center Fire Caliber: 17 Customer: Destination: EDWARD FONK Arms Services BOX 187 212 N. 4TH 14 Hoefler Ave MANHATTAN, MT 59741 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 7335 Parts And Service Details

Qty Needed Warranty

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

Price

Disc Amount

.00

ARS LABEL REQUEST FORM

DATE:	01/27/2012	Service Request #	SR00011165
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
<u> </u>			

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

EXECUTE OF WAY TO VE		
MAIL LABEL TO:	EDWARD FONK BOX 187 212 N. 4TH MANHATTAN, MT 59741 US SR00011165 Email:	
RETURN ITEM TO:	ILN Arms Services	



4XX596 JAN 30, 2012 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969066472905 REF 1:SR00011165 REF 2:

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 CD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 13.52 PUB+HANDLING 13.52

ATTN: Product Service

