Remington Arms Co., Inc. Product Service Legal Case #:7215

Case Info	ormation										
RE # 255926		Opened 5/2012	Date Openeo 1/4/2012		e Closed 26/2012	Incid	lent Dat	e	Pre Lit	Lit	Obsolete
Customer	r Informatio	on									
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	C	Contac	t
Incident		Willard	Hafer	2507 May Ln.	La Grande	OR	97850		H 54 E bhafer6	1-963- 9@hot	
Incident 1	Information	1									
Claims			Codes		Repai	r Est.	Medi	cal Ti	reatment	Medi	cal Status
PI											
PD S C FBC	Cond	e:4006 Alte cern:1008 Fire		nts or Compone sing	nts		τ	Jnkno	own		
reported.	df	·····	ight gun used.	He stated his so	on had a FBC	late las	at year w	hile u	ising. No da	image	or injury
	nformation	Ŀ.									
	lfg.		Туре	_	Model/Ga.		SKU		Serial	Bbl.	DOM
	ington	XX 71	CF/BA		/3006 SPRG	<u>.</u>	n/a		6632983	СХ	4/1/1973
	archased		ere Purchase IS PITTSBUR		ccessories	Uri	ginal O [.] N	wner			
CONCEF	RN: FBC										
Ammunit	tion Inform	ation - None I	Defined								
Other Pro	ducts Infor	mation - None	e Defined								
Settlemen	nt										
				Remington/7	/00/CF/BA		•				- ·
Sett	lement	Release	of Claims	Release Da	ite Rein	iburse	ment	Ca Settle	sh R ment Dat	eim. e APV	Cash , Date APV
	n - Quote to inder BLM										

Repair/Replacement Repair/Replacement Cost Date \$29

1/8/12: Mailing ARS & forms. Box order# 1293973. df 1/30/12: Per Ilion - TA set screws altered. Trigger not returning properly. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		1/26/2012	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
	Assigned To		T.NAGLE	-

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7215&Type=Case

2/6/2012

4

Cause	4006	Altered Adjustments or Components	
	Description		22" 3006 SPRG
	Date Code	1	CX
	Bore Plugged	False	
Barrel	Bulged	False	
Darrei	Fired	False	
	Fired while Obstructe	d	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
U	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.007
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
Trigger	Pull	Select	3#
	Altered	Тгие	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7215&Type=Case

2/6/2012

January 4, 2012

Willard Hafer 2507 May Ln. La Grande, OR 97850 Phone: 541-963-4481

Ref: # 7215, Model 700, Serial # 6632983

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,

Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC Phone: 1-800-243-9700 press 0 and ask for ext 8686 Fax: 336-548-7872

enclosure



T.A. Set screws Altered Trig. Not returning prop. Rymae TAA, cleAR+ Dest under BLP for \$ 20.+ Olcole JAN 3 0 2012

BY:

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

· Willard Wager 3507 Thay Lo Jagrande, OR 97850

blear Sir -During hienting Season this year, this rifle discharged upon closing the bolt. If you find a trigger problem or not, Owould gue more comfortable if you would replue it used the new trigger-safety xituation When the newer models, which can be opened and closed with the Difety on. Decase above of options and cost.

Amerily. Willard Alaper 541-963-4481

Model Number:	Serial Number:				
700	6632 983				
Name: Willard Hafer	Date of Purchase:				
Address (no P	O Boxes):				
100 2507 May L	gne e				
City: Labraude	State: 0 R Zip: 92850				
Phone (Daytime): <u>54/963-448/</u>	Fax:				
E-mail Address:	r 69@ hotmail.com				
Please describe y					
Discharged & upon closing the Bolt					
500 chara	cters left				
NOTE: Prior to shipping your firearm, con provided and estimation					
 WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. 					
Print	Reset				

http://www.remington.com/asp/general_repair_form.asp

1/4/2012

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700 www.Remington.com



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number SR00008865 Customer: WILLARD HAFER 2507 MAY LN	6632983 Model 700 Center Fire Caliber: 3006	Destination: Arms Services 14 Hoefler Ave	Date	Request: Printed:	01/08/2012 01/08/2012
LA GRANDE, OR 97	830 08	Ilion, NY 13357	02		
Email:		Email:			
Your request for service on the returned. If not, you will be co	e item(s) will be evaluated by our repairman to determine if in ontacted with an estimate before work is performed.	t is covered under our warranty pol	icy. If it is	your firearm	will be repaired and
	PRODUCT SERVICE FOR INSPECTION				
Service Request Section Product Service # 7215 - F					
Parts And Service Details Material Type	Description .	Qty Warranty Needed		Price	Disc Amount
					· .
			.•		
THIS IS NOT AN INVOICE. This is not being sent based on the convert	This is a pre-estimate to repair, recondition, or replace the ite sation with our representative.	m(s)		b Total: : Sales Tax:	.00 .00
	· · ·		Gr	and Total:	\$.00

ARS LABEL REQUEST FORM

DATE:	01/08/2012	Service Request #	SR00008865
QUANTITY:	I	WEIGHT PER PACKAGI	E: 10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com	
		LABEL INFORMATION	
MAIL LABE	L TO:	WILLARD HAFER 2507 MAY LN LA GRANDE, OR 97850 US SR00008865	
		Email:	
RETURN I	TEM TO:	ILN	
		Arms Services	
		4XX596 JAN 9, 2012 AI SVC GNDCOM BL WT 1 Tracking# 1Z4XX5969065021591 Ref 1:Sr00008865 Ref 2:	CT WT 10.0 LBS #PK 1 10.0 LBS All Currency USD
ATTN: Pro	duct Service	HANDLING CHARGE 0.00 SHIPMENT PUB RATE CHARGES: DV 0.00 COD 0. DC 0.00 DGD 0.	FRT: 3RD SVC T/P USD .00 RS 0.60 .00 ROD 0.00 .00 ROD 0.00 UB+HANDLING 12.74



PS 27867



