

Remington Arms Co., Inc.									
Product Service									
Case # 7176									
Case Information									
RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete		
250766	12/16/2011	12/30/2011	1/3/2012						
Customer Information									
Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bob Ward & Sons			3015 Paxson St	Missoula	MT	59801		W 406-728-3220
Incident	customer name:	Tamara	Hatch	10250 Bear Run Creek Rd	Missoula	MT	59803		H 406-251-3365
Incident Information									
Claims	Codes	Repair Est.	Medical Treatment	Medical Status					
PI									
PD	Cause:4038	Could Not Duplicate Concern							
S	fired on bolt closing	Concern:1008	Fired on Bolt Closing		Unknown				
C									

per note: gun fired when closing bolt.

Firearm Information							
Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM	
Remington	CF/BA	700/3006 SPRG	27269	S6524378	PZ	6/3/2005 7:27:48 AM	
Date Purchased	Where Purchased	Accessories	Original Owner				
	CSI SPORTS. LLC	TWO PIECE BASE	U				

CONCERN:FBC

Ammunition Information - None Defined							
Other Products Information - None Defined							
Settlement							
Remington/700/CF/BA							
Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV	
Replace TPA at 1/2 normal cost							
Repair/Replacement Cost	Repair/Replacement Date						

per lition: could not duplicate concern. can offer to replace TPA, clean & test fire at 1/2 normal cost.

Examination[Remington/CF/BA]			
Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 3006 SPRG
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	SOME RUST IN ACTION
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.014
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

place 1917

BOB WARD

& Sons

COMPLETE SPORTING GOODS CENTERS

Missoula • Hamilton • Bozeman • Butte • Helena

11679

776

Date 12 / 1 / 11

Select one:

☐ Store Stock Repair Order

☒ Customer Repair Order

Customer Name: Tamra Hatch

Address: 10250 Bear Run Creek Rd

City: Missoula State: MT Zip: 59803

E-mail Address: _____

Phone: 406-251-3365

Item Description

Brand: Remington

Style #: 700 SPS

Style Name: _____

Color: syn stock

Size: 30.06 serial # S6524378

Repairs Needed: Gun Fired when closing

Bolt

Sales Associate: BILL BROWN

Contact Person: _____

Bob Ward & Sons - Returns Department

☒ 3015 Paxson Street
Missoula, MT 59801
(406) 728-3220

☐ 3011 Max Avenue
Bozeman, MT 59718
(406) 586-4381

☐ 1120 North 1st Avenue
Hamilton, MT 59840
(406) 363-6204

☐ 3323 Dredge Drive
Helena, MT 59601
(406) 443-2138

☐ 1925 Dewey Blvd.
Butte, MT 59701
(406) 494-4452

☐ .com
1609 North Avenue, Suite 500
Missoula, MT 59801

D - Vendor Copy

Serial Number: **S6524378**

Model: **700**



RE00250766

could not duplicate concern
can often to replace TPA, clean
+ test fire at 1/2 normal cost.

Quote

RECEIVED
JAN - 4 2012

BY: _____

24"
P26/05
6th
014

Fax 406-728-5230





