Remington Arms Co., Inc. Product Service Legal Case #:7388

Case Information

RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 258216 2/10/2012 2/13/2012 2/13/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact 1792 Northstate Hwy F Incident Don Jett Ash Grove MO 65604 E jettashgrove@aol.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Unknown S Fired out of battery Concern: 1021 Fired Out of Battery

2/24/12

Firearm Information

Mfg. Type Model/Ga. SKU Serial DOM Remington CF/BA 700/270 WIN n/a B6493959 DD 9/1/1983 **Date Purchased** Where Purchased Accessories Original Owner

J C PENNEY STATESVILLE NC U

CONCERN: FIRED OUT OF BATTERY

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Settlement Date APV Date APV

Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

2/28/12 Per Ilion, could not duplicate concern. Can offer to replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		2/13/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		DD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	-
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	

httn://cnc03an13:200/ncaann/PrintDienlay acny?ID=7388&Tyne=Cace

2/28/2012

Bolt	F	lov 1.1 TV F	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Se	rvice	Rec	west
JC	IAICC	NGU	ucol

Remington Service PO Box 700



12/09/2011

12/09/2011

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336_248-7801 www.Remington.com
This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description SR00006271 B6493959 Printed: Model 9 Customer: DON JETT 1792 NORTHSTATE HWY F Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US ASH GROVE, MO 65604 US Email: JETTASHGROVE@AOL.COM Email: Your request for service on the itera(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M295 - EVALUATE AND REPAIR

Service Request Section

FIRED OUT OF BATTERY TWO YEARS AGO. JJT

SENT ARS

Paris And Service Details

Material

Description

Qty Needed Warranty

Disc Amount Price

B6493959



could not duplicate concerns case often to reprose TPA, Cernic Dor At 1/2 respondess.

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00 .00

\$.00





