

Remington Arms Co., Inc.
Product Service
Legal Case #:7594

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265100	4/18/2012	4/19/2012	4/19/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Jim's Hobby	---	Jim's Hobby	401 South Dewey St.	North Platte	NE	69101		W 308-534-3225

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Dealer sent rifle in w/note. Dealer stated sometimes trigger works and sometimes it doesn't and sometimes it fires when releasing trigger. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6722775	LY	2/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	HH SPING GDS CO AMARILLO TEX	SCOPE BASE,RINGS	U			

CONCERN: SOMETIMES TRIG WORKS SOMETIMES IT DOESN'T

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

4/26/12: Per Ilion - TA dirty & sticky. Parts work sluggish. Replace TA, clean & test fire under BLM - quote. df 5/2/12: Dealer apprvd & paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/19/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		LY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE, RINGS

JIM'S HOBBY
401 South Dewey Street
NORTH PLATTE, NEBRASKA 69101
(308) 534-3225

7594

22"
4 1/2" 74
4.5"
.005

CUSTOMER'S ORDER NO. 786 PHONE DATE 4-11-2012

NAME Remington Arms Co

ADDRESS 14 Hoefler Avenue

Sharon New York 13357

SOLD BY CASH C.O.D. CHARGE ON ACCT. MDSE. RET'D. PAID OUT

QTY. DESCRIPTION PRICE AMOUNT

1 Remington 700 BDL 30/06
Ser # 6722775

Dear Sirs;

Thank

786 Remington

Sometimes trigger works

and sometimes it doesn't

and sometimes it fires

when releasing trigger.

Model: 700

RECEIVED
APR 26 2012

BY:.....

THANK YOU

T.A. dirty + sticky. parts
work sluggish. Replace TPA,
clean + test under BCP load
820 +

Q note







