Remington Arms Co., Inc. Product Service Legal Case #:7326

Case Information

Date Opened Date Opened(PS) RE# Date Closed **Incident Date** Pre Lit Lit Obsolete 257797 2/8/2012 1/25/2012 2/9/2012 11/16/2011

Customer Information

Type Business First Name Last Name Street City State Contact Zip Age 2905 W. Piney Ln. C 906-362-1449 Reporter Arthur Jodoin Spalding 49886 PO Box 172 F 906-250-0062

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PI

PD Cause:4038 Could Not Duplicate Concern S FBC Concern: 1008 Fired on Bolt Closing

Unknown

C

1/25/12: Customer called in. He stated his son was using the rifle on 11/16/11 & when he closed the bolt it fired. No damage, No injury. Customer wants bolt lock modification done. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM A6274785 AI 3/9/1976 n/a

CF/BA 700/3006 SPRG Remington Date Where Purchased Accessories Purchased

Owner

CLEARFLD HDWE TWO PIECE BASE, AFT MKT **CLEARFIELD PA**

STK

N

Original

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Date Reimbursement Settlement Date APV APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost Date

> > \$30

1/26/12: Mailing ARS & forms. Box order# 1300964. df 2/15/12: Could not duplicate concern. TA dirty. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/9/2012
	Product Type		RF
	Action Type		A

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7326&Type=Case

2/20/2012

.	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	n]
Barrel	Description		22" 3006 SPRG
	Date Code		AI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Conditi	ion Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
-	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	7
	Ext/Eject Test	False	
,	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	1
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	1
Overall	Stock Condition	Select	AFT MKT
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.007
	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	7.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components Description			TWO PIECE BASE, AFT MKT STK

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

,00

Service Request Number

Serial Number / Description

A6274785

Model 700 Center Fire Caliber: 3006

Date of Request: 01/26/2012 01/26/2012 Printed:

Customer:

SR00010971

ARTHUR JODOIN 2905 W. PINEY LN. PO BOX 172

SPALDING, MI 49886 US

Email:

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section Product Service # 7326

Parts And Service Details Material

Description

Qty Needed

Disc

Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

Model Number:	Serial Number:						
1 700	A 6274785						
Name: ART Jodoin	Date of Purchase:						
Address (no PO Boxes):							
2905 W PINEY LANE							
City: Spalding	State:						
Phone (Daytime): 906-362-1449	Fax: 406- 250-0062						
E-mail Address:							
Please describe y	our problem:						
MIS-FIRES							
500 chara	cters left						
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.							
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.							
Print	Reset						

ARS LABEL REQUEST FORM

DATE:	01/26/2012	Service 1	Request #	SR00010971
QUANTITY:	1	WEIGH	T PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email ad	dress:	I WILL MAIL LABEL
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com		
		LABEL INFOR	MATION	
MAIL LABE	L TO:	ARTHUR JODOIN 2905 W. PINEY LN. PO BOX 172 SR00010971 SPALDING, MI 49886 US Email:	3	
RETURN IT	EM TO:	ILN Arms Services		
		4XX596 JAN 26, 2012 SVC GNDCOM BL WT TRACKING# 1Z4XX5969065774920 REF 1:SR00010971 REF 2: HANDLING CHARGE 0.00 SHIPMENT PUB RATE CHARGES: DV 0.00 COD DC 0.00 DGD AH 0.00 PR TOT PUB CHG 10.31	FRT: 3RD SVC T/P I 0.00 RS (0.00 0.00 ROD (USD 0.50

ATTN: Product Service

PS 28155





