Remington Arms Co., Inc. Product Service Legal Case #:7587

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 266119 4/30/2012 4/16/2012 5/1/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact Incident Mitchell 3526 W Morrow Dr H 623-581-7383 Johnson Glendale AZ85308

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status

PΙ

PD Could Not Duplicate Cause:4038 Concern Fired when releasing

Unknown

safety

Concern:1007 Fired on Safe Release

С

4/16/12 Per call from Mitchell, last wife his wife was going to shoot at a deer and if fired when she flipped the safety off. He has cleaned it and checked it since and it looked clean.cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/30-06 SPRG

SKU 25634

Serial B6780941 Bbl. CG

DOM 4/22/1986

Date Purchased

Where Purchased **UDISCO**

Accessories

Original Owner

N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Cash Reim. Date

APV

Date APV

Per Ilion, replace TPA, clean, test at no charge

Repair/Replacement Repair/Replacement

Cost

Date

47.40

5/7/2012

4/16/12 Mailing ARS.cm 5/7/12 Per Ilion, could not duplicate concern. Trigger assm dirty and pull screw altered. Safe works very hard. Replace TPA, clean, test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/1/2012
	Product Type		RF
	Action Type		A

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7587&Type=Case

5/7/2012

	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code	1	CG
	Bore Plugged	False	
	Bulged	False	
	Fired	False	1
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	7
	Block Condition	Select	7
Locking	Lug Condition	Slightly Worn; Functioning	7
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	GLASS BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	Ī
	Bulged	False	Ī
Safety	Description		M/700 SAFETY
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	7
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY, SAFE WORKS VERY HARD
L.	Pull	Select	2.5#
Trigger	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

COPY

April 16, 2012

Mitchell Johnson 3526 W. Morrow Dr Glendale, AZ 85308

Subject: Case # 7587, Model 700 Barrel, SR# 17556


Dear Mr. Johnson,

Enclosed is a prepaid shipping label to cover shipment of the firearm to our factory for inspection. Please include a copy of this letter with it as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the product is logged in correctly. Please mark the small ends of the boxes "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com





could not dy concern.

T.A.dinty & pull scruw Altered.

SACe works very hand.

Approxe TPA, element out AT

N/c # 230145

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700 ATTN: Prod Serv #7587

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN**.

Service Request Number

Serial Number / Description

SR00017556

B6780941

Model 700 RIFLE

Customer:

MITCHELL JOHNSON 3526 W MORROW DR GLENDALE, AZ 85308 US

Email: Christy

04/16/2012

Date of Request:

Date Printed:

04/16/2012

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Fired when releasing safety.cm

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

Pric

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

	······································
Model Number: 700	Serial Number: B678094/
Are you the original owner?: YES X NO	
Name: Mitchell Johnson	Date of Purchase: 1.996
Address (no PO Boxes): 3526 (U.)	Morrow Dr.
City: Glendale	State: Az Zip: 85308
Phone (Daytime): 623-581-7383	Fax:
E-mall Address:(if e-mail address is provided, notifica	etion of receipt and shipment will be
senti) MMJ737@AO	L. Com
E-mail Address:	
I would like to receive future e-mail updates from	Remington.
Please describe your problem and date of occurre	iryte:
13	2011 We had a
Many going on,	Twice on that hunt,
"off safe " one to	on the ville disclarger
19150 Plus Softi	
Safe to off safe	y bee 20 to 30 vounds
The nile gots me	ry bee 20 to 30 vounts
500 M Your Harough it	
Ammunition Information:	
Manufacturer Federal	Type: Palor Shok
Other (i.e. bullet weight/type, shot size, powder):	180gr
·	- V.
Handload Information:	
Powder Used:	Powder Weighi:
Case/Huli Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Butch's Pose Shine
How often do you clean the bore? (Montins or Number of rounds) Carly Wange Session 2
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds) 12 months
Brand of Jubricant used: M-Pvo 7.
How often do you lubricate the bore? (Months or Number of rounds) and pange gossian
How often do you lubricate the action? (Months or Number of rounds) Each vauge Sossion
How often do you lubricate the trigger assembly? (Months or Number of rounds) 12 menths
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized
repairman/gunsmith?) Nover
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefier Avenue Illon, NY 13357
THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
Record the serial number of your firearm before sending it. Peck your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

ARS LABEL REQUEST FORM

DATE:	04/16/2012	Service Request #	SR00017556
QUANTITY:	1 :	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelles	email address:	Christy.Mitchell@remington.com
•			
			•

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

MITCHELL JOHNSON 3526 W MORROW DR GLENDALE, AZ 85308 US SR00017556

Email: Christy

RETURN ITEM TO:

ILN

Arms Services



4XX596 APR 16, 2012 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969066658563 REF 1:5R00017556 REF 2: 1 OF 1

13.52

HANDLING CHARGE 0.00

SVC T/P USD 0.00 RS 0.50 SD 0.00 0.00 SD 0.00 0.00 SP 0.00 PUB+HANDLING 13.52

ATTN: Prod Serv #7587

PS 28180

JOHNSON'S GUN DEPOT

PA 48

2231 Mt. Pleasant Road - Box 175 Norvelt, PA 15674

Phone: 724.423.1100 Fax: 724.423.1454

email: guns@zoominternet.net ---- www.johnsongundepot.com

Date: 7/9//2 RMA # (If needed)
TO: REMINGTON ARMS SERVICE
Address: SR+ SR00023508 14 HOEFLER AVE
City: <u>TLION</u> State: <u>NY</u> Zip: <u>/3357</u>
Attention: REPAIR
Dear Sir or Madam:
We are sending the following firearm to you:
Make: REMINGTON Model: 700 BDL Serial: 680490 2 Caliber/Ga 270
for:
The following is a description of the problems with this firearm or the work that is needed to this firearm: Closel Bolt releasel. Safety
Gen fued prematurely
PECETVED JUL 1 9 2012
B62251/6
Model: 700 could not dup l'este concern
T.A. LIRTY, Replace TPA, CLEBNZ
RE00274363 Test under BLP Lon & 20. + Ship
RE002/4303
Your prompt cooperation in handling this fireram is sincerely appreciated. If you have any need to contact us concerning this fireram, please direct your call to me. Thanks again.
Representative of Johnsons Gun Depot





