Remington Arms Co., Inc. Product Service Legal Case #:7253

Case Information

RE# Obsolete **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit 255936 1/25/2012 1/10/2012 1/26/2012 1/7/2012 Х

Customer Information

Type Business First Name Last Name City State Zip Age Street Contact C 937-545-2964 Joe Johnston

8180 Myers Rd. Middletown OH 45042 E jjohnston12@cinci.rr.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

PΙ

PD Cause: 4013 Broken or Missing Parts S FSR Concern:1007 Fired on Safe Release

Unknown

C

1/10/12: Customer called in. He said he has never done anything but clean the barrel. He stated he had FSR on 1/7/12. No damage or injury reported. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM 5/2/2001 700ML/50 CAL 27586 Remington ML/BA ML238561 11:41:24 PM

Date Purchased

Original Where Purchased Accessories Owner

ACUSPORT (OH) AFT MKT 209 FIR PIN CORPORATION AND NIPPLE

Y

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700ML/ML/BA

Cash Reim. Date Cash Date Release of Claims Settlement Release Date Reimbursement Settlement APV APV

Per Ilion - Repair @ n/c

> Repair/Replacement Repair/Replacement Cost Date

\$34

1/10/12: Customer wants ARS & forms emailed to him. Box order# 1295090. df 1/30/12: Per Ilion - Connector broken. Replace TA, check over at n/c. df

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/26/2012
	Product Type		RF
	Action Type		A

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7253&Type=Case

2/6/2012

	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	CONNECTOR BROKEN
Barrel	Description		24" 50 CAL
	Date Code		KV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Select	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Select	<u> </u>
	Handle	Slightly Worn; Functioning	
	Stop	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10515	False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT 209 FIR PIN AND NIPPLE

24" (U 5/0

7253

January 10, 2012



Joe Johnston 8180 Myers Rd.

Middletown, OH 45042 Phone: 937-545-2964

Email: jjohnston12@cinci.rr.com

Ref: #7253, Model 700ML, Serial #ML238561

You will receive a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination in a separate email. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

ML238561
Model: 700ML
PE00255924

CONFEITON BROKEN.

Rephra TPA, checkoven

10 T IV/c DEGETTED

#230141 JAN 30 2012

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

### Service Request

## Remington Service PO Box 700



Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description Date of Request: 01/10/2012 SR00009223 ML238561 Date Printed: 01/17/2012 Model 700ML RIFLE Caliber: 50 Customer: IOE JOHNSTON Destination: Arms Services 8180 MYERS RD 14 Hoefler Ave MIDDLETOWN, OH 45042 US Ilion, NY 13357 US Email: jjohnston 12@cinci.rr.com Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and teturned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 7253 - FSR Parts And Service Details Material Type Price Disc Amount Description Qty Warranty Needed THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) Sub Total: .00 being sent based on the conversation with our representative. Est Sales Tax: .00 General Repair Form Page 1 of 1

\*\*Gun Fires w/o pulling triggen, when taking safety of Serial Number: **Model Number:** 700 ML ML 238561 **Date of Purchase:** Name: JOE JOHNSTON Bought NEW ? DATE! Address (no PO Boxes): 8180 MYERS City: MIDDLE TOWN State: OH Zip: 45042 Phone Fax: (Daytime): 937-545-296 E-mail Address: jiohnston 12@ cinci. M. com Please describe your problem: GUN FIRES MOST OF THE TIME When You take the SAFETY OFF. Also trigger is set very light (hairtrigger). I bought this gun new and have never had anything altered on fixed. Very DANGEROUS GUN! NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time. WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM, THIS IS A **VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT** SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss --- during shipment, so you may elect to purchase insurance from your carrier. Print Reset # I purchases this gun new around 2001-2003 OFF OF OLD English our Shop in Tipp City NAMODALIA, OH http://www.remington.com/asp/general repair form.asp 1/4/2012 and and rem appoint

# Remu gton.

January 10, 2012

Joe Johnston 8180 Myers Rd. Middletown, OH 45042 Phone: 937-545-2964

Email: jjohnston12@cinci.rr.com

Ref: #7253, Model 700ML, Serial # ML238561

You will receive a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination in a separate email. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number:	Serial Number:				
Name:	Date of Purchase:				
Address (no PO Boxes):					
City:	State: Zip:				
Phone (Daytime):	Fax:				
E-mail Address:					
Please describe y	our problem:				
500 chara	cters left				
NOTE: Prior to shipping your firearm, co provided and estima					
WARNING: DO NOT SEND LIVE FIREARM OR IN THE SAME BOX W VIOLATION OF FEDERAL LAW. IF YO SHELLS PLEASE SEND THEM IN A SEI NAME, ADDRESS (WITH ZIP CODE), SERIAL NUMBER OF  :: Record the serial number of yo :: Pack your firearm for safety and to pre- handling. Prefera	VITH THE FIREARM. THIS IS A U FEEL YOU MUST SEND SPENT PARATE PACKAGE AND INCLUDE TELEPHONE AND MODEL AND YOUR FIREARM.  ur firearm before sending it. vent further damage in shipping and				
firearm box. (Note: Original b :: Remove all accessories from your fi :: Ship your INSURED firearm by either U responsible for da - during shipment, so you may elect to p	oxes may not be returned.) rearm to prevent loss or damage. IPS or Parcel Post. Remington is not mage or loss				
Print	Reset				

#### Fulcher, Dell Marie

From:

To: Sent:

Subject:

postmaster@remington.com jjohnston12@cinci.rr.com Tuesday, January 10, 2012 2:36 PM Relayed: Message relayed (jjohnston12@cinci.rr.com)

Delivery to these recipients or groups is complete, but no delivery notification was sent by the destination server:

jjohnston12@cinci.rr.com

Subject:

#### ARS LABEL REQUEST FORM

DATE:	01/10/2012	Service Request #	SR00009223
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	
Business:		Remington Service	
		PO Box 700 Madison, NC 27025-0700 www.Remington.com	

#### LABEL INFORMATION

	LABEL INFORMATION
MAIL LABEL TO:	JOE JOHNSTON 8180 MYERS RD MIDDLETOWN, OH 45042 US SR00009223 Email: jjohnston12@cinci.rr.com
RETURN ITEM TO:	ILN Arms Services

4XX596 JAN 10, 2012 ACT WT 10.0 LBS #PK 1
SVC GNDCOM BL WT 10.0 LBS #PK 1
THACKING# 1Z4XX5969065438356 ALL CURRENCY USD
REF 1:SR00009223
REF 2:

HANDLING CHARGE 0.00 FRT: 3RD
SHIPMENT PUB RATE CHARGES: SVC T/P USD
DV 0.00 COD 0.00 RS 1.00
AH 0.00 PR 0.00 ROD 0.00
TOT PUB CHG 9.54 PUB+HANDLING 9.54

ATTN: Product Service