

Remington Arms Co., Inc.
Product Service
Legal Case #:7867

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
277701	8/7/2012	8/21/2012	8/21/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Robert	Paolini	120 Lake Warren Rd.	Upper Black Eddy	PA	18972		E bp921@aol.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			Unknown
S	Gun went off Concern:1025 Unexplained Discharge - No Mention of Safety Position			
C				

Customer sent rifle in. Repair had comments that "gun went off". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6270567	LI	2/27/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	NATWIDE SPTS SOUTHAMPTON PA	AFT MKT STK	U			

CONCERN: GUN WENT OFF

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

8/22/12: Per Ilion - TA dirty & sticky. Set screws altered. Replace TA, clean & test fire under BLM - quote. df 8/23/12: Customer called into Consumer Service Dept - apprvd quote & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/21/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPRG
	Date Code		LI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		AFT MKT STK

frmREInquiry - Repair Inquiry

Repair Number: **RE00277701**

Serial: A6270567 Model 700 Center Fire Caliber: 30 - 06 Produced: 02/27/1976 SKU: 20000

Repairman:

Verify Repair

Status: New 7/31/2012 11:13:55 AM

7867

ADDRESS INFORMATION

Customer		Received from	Return To		Received from
Name:	ROBERT PAOLINI		Name:	ROBERT PAOLINI	
Address 1:	120 LAKE WARREN RD		Address 1:	120 LAKE WARREN RD	
Address 2:		PO Box:	Address 2:		PO Box:
City:	UPPER BLACK EDDY		City:	UPPER BLACK EDDY	
State:	PA	Zip Code:	State:	PA	Zip Code:
	18972	Country:		18972	Country:
	US			US	

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone:
Fax:
Email: BP921@AOL.COM
Comments: GUN WENT OFF

Received Condition

Good
Condition Notes:
CSR Notes: GUN WENT OFF

Accessories Received

Code	Desc	Qty
A007	With Stud	2

T.N. dirty & sticky. self screws altered. replace TPA, 2 leaves test water BLR Con B 20. +


Q

Refresh

Close

A6270567

Model: 700



RE00277701

RECEIVED

AUG 22 2012

BY:

TUESDAY, AUG 21 2012 LASRPRT1

5:35 AM

Tuesday, Aug 21 2012

5:38 AM

22"
LI 2/76
4#
005







