

## Remington Arms Co., Inc.

Product Service

Legal Case #:7436

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
259608	2/23/2012	2/24/2012	2/24/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Pattens Sporting Goods	---	Pattens Sportin	2956 Dartmouth College Hwy	North Haverhill	NH	03774		W 603-787-6964 E spatten@pattenssportinggoods.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			
S FSR	Concern:1007 Fired on Safe Release		Unknown	
C				

Dealer sent rifle in. Repair form stated the rifle sometimes fires when the safety is moved from Safe to Fire. Dealer stated they were returning the gun for the safety modification program. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	6345060	PT	6/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	PARKER DIST N ROCHELLE NY		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

2/27/12: Per Ilion - TA very dirty & set screws altered. Trigger not returning properly. Replace TA, clean & test fire under BLM - quote. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/24/2012
	Product Type		RF
	Action Type		A

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7436&Type=Case>

3/7/2012

	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 22-250 REM
	Date Code		PT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

7436

24"  
PT6/70  
3.5"  
.006

<b>Model Number:</b> 700 ADL		<b>Serial Number:</b> 6345060	
<b>Name:</b> Patten's Sporting Goods		<b>Date of Purchase:</b> Unknown	
<b>Address (no PO Boxes):</b> 2956 Dartmouth College Highway			
<b>City:</b> North Haverhill		<b>State:</b> NH	<b>Zip:</b> 03774
<b>Phone</b> (Daytime): 603-787-6964		<b>Fax:</b> None	
<b>E-mail Address:</b> spatten@pattenssportinggoods.com			
<p align="center"><b>Please describe your problem:</b></p> <p>This firearm sometimes fires when the safety is moved from "SAFE" to "FIRE".</p> <p>We are returning it for repair under the "Safety Modification Program". We understand that there will be a \$20 charge for this repair. The firearm should be returned to the address above.</p> <p align="right"><i>T.A. very dirty + set screws altered. Trigger not set properly. replace TPA, clean + test under T.C.P. R. 20 +</i></p> <p align="right">231 characters left <i>Quote</i></p>			
<p><b>NOTE:</b> Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.</p>			

RECEIVED  
FEB 27 2012

BY: \_\_\_\_\_

Serial Number:  
6345060  
Model: 700

RE00259608

IF YOU HAVE FIRED OR SPENT SHELLS IN YOUR  
FIREARM, THIS IS A  
REPAIR CENTER. IF YOU FEEL YOU MUST SEND SPENT  
SHELLS, PLEASE SEND IN A SEPARATE PACKAGE AND INCLUDE  
A LIST OF THE SHELLS (CALIBER, TYPE, QUANTITY), TELEPHONE AND MODEL AND  
LOCATION OF YOUR FIREARM.

Remove all accessories from your firearm before sending it.  
To prevent further damage in shipping and handling, ship in a  
hard container (boxes may not be returned.)

- Remove all accessories from your firearm to prevent loss or damage.
- Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset







