

Remington Arms Co., Inc.
Product Service
Legal Case #:7883

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
279470	8/22/2012	8/22/2012	8/22/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Puglia's		Puglia's	1925 Veterans Memorial Blvd	Metairie	LA	70005		W 504-837-0291

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fires without trigger being pulled	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

9/6/12 Per note with rifle, gun fires without trigger being pulled. Missing hood for front sight.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6801229	EV	10/18/1979
Date Purchased	Where Purchased	Accessories	Original Owner			
	STRATTON/BALD ST ROSE LA	SEE THRU RING MOUNTS	U			

CONCERN: FIRES WITH PULLING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	87.31	9/6/2012				

9/6/12 Per Ilion, could not duplicate concern. Trigger assm dirty, rusty. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/22/2012
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		EV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	RUST UNDET STOCK
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	--Select--	4.75#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SEE THRU RING MOUNTS

1925 VETERANS MEMORIAL BLVD.
METAIRIE, LOUISIANA 70005
PHONE: (504) 837-0291 FAX: (504) 837-0586

DATE:

8/16/12

TO:

Remington

REFERENCE:

SN: A6801229

MESSAGE:

Gun fires w/o trigger being pulled
Missing hood for front sight.

Thanks

Amanda

Serial
Number:

A6801229

Model: 700



RE00279470

RECEIVED
AUG 27 2012

BY:

could not dup. concern.
T.A. dirty & rusty. Replace TPA,
clean & test fire under BLP
Con & 20. + ship

Quote



7883

22"
EV10/79
4.75"
.009





