

Remington Arms Co., Inc.
Product Service
Legal Case #:7614

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265456	4/24/2012	4/25/2012	4/25/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sanilac County Sheriff's Office	Steve McKenny	Sanilac County	65 North Elk St	Sandusky	MI	48471		E stevedtr89@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			
S	Fired when safety removed Concern:1007 Fired on Safe Release		Unknown	
C				

5/10/12 Per note on SR, gun has fired when safety removed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25715	D6264583	BS	1/16/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
	MICHIGAN POLICE EQUIPMENT		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

5/10/12 Per Ilion, trigger assm set screws altered. Trigger not returning properly. Replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/25/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 308 WIN HB
	Date Code		BS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFTEY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P-800-243-9700/F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

26"
B51/98
3#
2011

Service Request Number SR00016626	Serial Number / Description D6264583 Model 700 RIFLE Caliber: 308	Date of Request: 04/02/2012 Date Printed: 04/02/2012
Customer: SANILAC COUNTY SHERIFFS OFFICE 65 NORTH ELK ST ATTN STEVE MCKENNY MI 48471 US Email: stevedr29@yahoo.com		Destination: Arms Services 14 Hoefer Ave Ilion, NY 13357 US Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return:
M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section:
gun has fired when safety removed

replace swing swivel stud
check Barrel for free floating

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:

D6264583

Model: 700



RE00265456

RECEIVED
APR 26 2012

BY:.....

T.A. set screws altered
TRIG. Not returning properly.
Replace TPA, clean test AT
1/2 normal cost.

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00





