

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7301

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
254988	1/19/2012	1/20/2012	1/20/2012				X

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Tudor Investment Group	Jim Hirsch	Tudor Investmen	1275 King St	Greenwich	CT	06831		E.jhirsch@tudor.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4031 Worn parts or components		Unknown	
S	Fires on safety release Concern:1007 Fired on Safe Release			
C				

1/25/12 Per note with rifle, on several occasions when going from safet to fire the weapon will discharge.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700/50 CAL.	27572	ML219460	KS	9/17/1999 9:38:06 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	AMERICAN ROD & GUN	AFT MKT FIR PIN,209 NIPPLE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, check at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	34.21	1/25/2012				

1/25/12 Per Ilion, connector worn/broken and is not connecting properly. Replace TPA, clean, check at no charge.cm

## Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4031	Worn parts or components	THE CONNECTOR APPEARS TO BE WORN/BROKEN AT EDGE FOR SEAR CONTACT.
Barrel	Description		24" 50 CAL
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	---Select---	
	Shroud	Slightly Worn; Functioning	
	Face	---Select---	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT FIR PIN,209 NIPPLE

# Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801 [www.Remington.com](http://www.Remington.com)

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

<b>Service Request Number</b> SR00009396	<b>Serial Number / Description</b> ML219460 Model 700ML RIFLE Caliber: 50	<b>Date of Request</b> 01/11/2012	<b>Date Printed</b> 01/11/2012
<b>Customer:</b> TUDOR INVESTMENT GROUP/ ATTN: JIM HIRSCH 1275 KING ST GREENWICH, CT 06831 US Email: <a href="mailto:jhirsch@tudor.com">jhirsch@tudor.com</a>	<b>Destination:</b> Arms Services 14 Hoefler Ave Ilion, NY 13357 US Email:		

24"  
1255/9

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep returned. If not, you will be contacted with an estimate before work is performed.

**Reason For Return**  
M992 - SAFETY

**Service Request Section**  
Gun fired when flipping from safe to fire

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

ML219460

Model: 700ML



RE00254988

CONNECTOR WORN/BROKEN  
IS NOT CONNECTING PROPERLY.  
REPLACE TPA, CLEAN & CHECK  
OVER AT N/C  
#230145

RECEIVED  
JAN 21 2012

BY: \_\_\_\_\_

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$ .00

January 12<sup>th</sup> 2012  
James N Hirsch Jr.  
9 Linden Place  
Greenwich, Ct. 06831

Arms Service  
SR#SR00009396  
14 Hoefler Ave.  
Ilion, NY 13357

Gentleman or ladies

Unfortunately I cannot locate my proof of purchase, but I do know that I purchased this Muzzle loader along with two others at the same time.

This would have been just prior to Christmas in either 2008 or 2009.

One was for me and the two others were for my sons. Both of my sons still have theirs. This is my reason for a heightened concern is this going to happen to theirs. Both of theirs have been check and function correctly.

However mine has a very scary problem. When going from safe to the fire position the weapon will discharge. The first time it happen my friend who was using the ML felt that he had never put his finger near the trigger.

We then reloaded the ML and once again when the safe was moved forward the weapon discharged.

This was tried by me at least three or four more with just using a primer and every time you move the safe forward the weapon fired.

The weapon was taken home cleaned and removed from the stock just to see if anything could be observed with the trigger mechanism. Nothing was observed in fact the security tap that covers two holes on the trigger mechanism was still in place and left there. It was then re-mounted back in the stock and is presently being packaged and shipped to you.

Many Thanks for anything you can do. My business card is attached and feel free to call me.

1275 King Street  
Greenwich, CT 06831

203.863.1839 telephone  
203.485.1387 facsimile  
917.747.5845 mobile  
254.378.8800 globevision

James Hirsch Jr.  
*James Hirsch Jr.*



**TUDOR**

INVESTMENT CORPORATION

Jim Hirsch  
Director of Security  
jhirsch@tudor.com