

Remington Arms Co., Inc.
Product Service
Legal Case #:7488

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
261747	3/14/2012	3/15/2012	3/15/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Wild West Guns	---	Wild West Guns	7100 Homer Dr.	Anchorage	AK	99518		W 907-344-4500 F 907-344-4005 E wildwestguns@alaska.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Slam Fires	Concern:1008 Fired on Bolt Closing		Unknown
C				

Dealer sent gun in for consumer. Dealer reported: Slam fires. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 RUM	n/a	S6340562	AT	3/1/1999
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN: SLAM FIRES

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

3/21/12: Per Ilion - TA set screws altered. Sear has min. engagement and will not connect properly. Can offer to replace TA, check over & test at 1/2 normal cost. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/15/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 300 RUM
	Date Code		AT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	SEAR ENGAGEMENT MIN, WILL NOT CONNECT.FOLLOWS DOWN
	Pull	---Select---	I#
	Altered	True	
	Sub-Assembly	M/700 Non-Bolt Lock	

7488
WILD WEST GUNS, LLC
Custom Gunsmiths
www.wildwestguns.com

26"
1#
AT3/99

Date: 3/5/2012 To: Remington

Our Reference Number: W08 9486

Return Authorization/Voucher Number: -

Item Serial Number: S 6340562

Enclosed Please Find:

Rem 700 300 R.U.M.

S6340562

Model: 700



RE00261747

Slam Firing - Please repair/replace.

Thanks!
-Hardy

T.A. set screws altered.
Serial has main engagement and
will not connect properly. Can
offer to replace TPA check
over & test at 1/2 normal cost.

Quote

PLEASE USE OUR REFERENCE NUMBER ON ALL INVOICES AND CORRESPONDENCE

THANK YOU!

7100 HOMER DR
ANCHORAGE, ALASKA 99518
PHONE (907) 344-4500 FAX: (907) 344 4005
TOLL FREE (800) 992-4570
wildwestguns@alaska.net

RECEIVED
MAR 21 2012

BY:









