

Remington Arms Co., Inc.
Product Service
Legal Case #:8799

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
307049	4/4/2013	4/12/2013	4/15/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Zachary	Verchimak	109 West Wall St	Ancona	IL	61311		H 815-674-1876 E zverchimak@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down			Unknown
S	Fired when moving from safe to fire Concern:1007 Fired on Safe Release			
C				

4/15/13 Per note on SR, "The last 3 out of 5 rounds fired, gun would discharge when moving from safe to fire."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	84218	G6770666	PC	6/27/2008 9:43:07 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC		U			

CONCERN: FSR

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	84218	G6770666		6/27/2008 9:43:07 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ZACHARY VERCHIMAK		U			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace with a new rifle of same model/caliber						

Repair/Replacement Cost Repair/Replacement Date

181.48	4/15/2013
--------	-----------

4/12/13 Per S. Nichols, contact owner for approval to replace with a new rifle of same model/caliber. Original will be sent to D. Watkins for inspection. Left voice msge for owner to call me. He left me a message that he is ok with the replacement but to call him before we do anything. I left another voice message for him afterward.cm 4/15/13 Received approval by phone call to Zachary.cm 4/23/13 Per email from D. Watkins, "we were able to duplicate the failure due to an extra spring being in the fire control, bag and tag the fire control and replace it with a new X-Mark Pro Adjustable."cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/12/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
		As received	

Cause	4054	Follows Down	
Barrel	Description		26" 308 WIN HB
	Date Code		PC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	TRIG MOVES AWAY FROM UNDER SEAR WHEN SAFETY IS MOVED OFF. ATTRIBUTE GAGE OVERRIDES SEAR WITH SAFE
	Pull	---Select---	N/A
	Altered	False	FACTORY SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		Derek Watkins
	Exam Date		4/16/2013

Examination	Product Type		RF
	Action Type		A
	Assigned To		
Cause	4058	Fired on Safe Release	The fire control was found to have an extra spring inside which was interfering with the function of the trigger. The claim was duplicated.
Barrel	Description		Like New, Functioning
	Date Code		Stamp too light to read
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	---Select---	N/A
	Ext/Eject Test	False	
Magazine	Condition	Like new; Functioning	
	Box Condition	Like new; Functioning	
Overall	Exterior Condition	Like new; Not Functioning	fire control not working
	Stock Condition	Like new; Not Functioning	fire control not working
	Fore End Condition	Like new; Not Functioning	fire control not working
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		
	Function	Like new; Functioning	
Tests	Test Fired	False	
	Feeding Test	False	
Trigger	Condition	Like new; Not Functioning	An extra spring was found between the back of the trigger and the trigger engagement screw.
	Pull	---Select---	not measured
	Altered	False	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

261
PC 6/1

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS YOUR RECORDS.

Service Request Number / Description SR00048964 G6770666 Model 700 RIFLE Caliber: 308	Date of Request 03/26/2013 Date Printed 03/26/2013
Customer: ZACHARY VERCHIMAK 109 WEST WALL STREET ANCONA, IL 61311 US Email: zverchimak@hotmail.com	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep. returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M295 - EVALUATE AND REPAIR/SAFETY INSP.

Service Request Section
THE LAST 3 OUT OF 5 ROUNDS FIRED GUN WOULD DISCHARGE WHEN MOVING FROM SAFE TO FIRE

Parts And Service Details		Qty	Warranty	Price	Disc	Amount
Material	Type	Needed				

Serial Number:
G6770666
Model: 700



RE00307049

RECEIVED
APR 15 2013

BY:.....

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00

Mega Sports, Inc.
23248 West Lincoln Hwy.
Plainfield, IL 60544
Ph: (815)436-1906 Fax: (815)436-2885

CALL STORE FOR
RETURN POLICY

MARK D. 2/22/2009 5:06:51 PM

REMINGTON 84218 MODEL 7 04770084218
LOG: 73924 SERIAL: 65770666

ZACHARY VERCHIMAK
109 W. WALL ST.
ANCONA, IL 61311
NTN # 1991236

Signature		574.99
NTCS & FTIP FEE	92092059	5.00
PAID IN FULL FIREARMS	20612	0.01

SUBTOTAL	580.00
SALES TAX1	46.00
TOTAL PURCHASE	626.00

REDACTED

Credit Card	626.00
Lway	0.00

ZACHARY VERCHIMAK
109 W. WALL ST.
ANCONA, IL 61311
815 674-1876

Signature

CHANGE 0.00

TRAN# 50300 STR# 001 REG# 2

STORE HOURS

Monday thru Friday 9 a.m. to 9 p.m., Saturday
9 a.m. to 6 p.m and Sunday 10 a.m. to 5 p.m

THANK YOU FOR YOUR
BUSINESS









