

Remington Arms Co., Inc.
Product Service
Legal Case #:8661

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
302049	2/26/2013	2/27/2013	2/27/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Nathaniel	Wood	1628 Burwell St	Bremerton	WA	98337		E nathanielwood@q.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when closing bolt	Concern:1008 Fired on Bolt Closing	Unknown	
C				

3/1/13 Per note with rifle, accidental discharge when bolt was closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	27363	G7045179	AF	3/9/2011 9:19:26 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ELLETT BROTHERS, LLC		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, will replace TPA, check over and test at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	50.20	3/1/2013				

3/1/13 Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, check over and test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/27/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 3006 SPRG
	Date Code		AF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P-800-243-9700 F-335-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

24 "
AF3/11
4.5"
1012

Service Request Number SR00045157	Serial Number / Description G7045179 Model 700 RIFLE	Date of Request: 02-14-2013 Date Printed: 02-14-2013																												
Customer: NATHANIEL WOOD 1628 BURWELL ST BREMERTON, WA 98337 US Email: nathanielwood@g.com	Destination: Arms Services 14 Hoeller Ave Ikon, NY 13357 US Email:																													
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.																														
Reason For Return M295 - EVALUATE AND REPAIR SAFETY INSP.																														
Service Request Section Accidental discharge with bolt was closed																														
<table border="1"> <thead> <tr> <th>Parts And Service Details</th> <th>Description</th> <th>Qty Needed</th> <th>Warranty</th> <th>Price</th> <th>Disc</th> <th>Amount</th> </tr> </thead> <tbody> <tr> <td colspan="7"> Serial Number: G7045179 Model: 700 RECEIVED MAR 01 2013 BY: _____ </td> </tr> <tr> <td colspan="7"> Barcode: RE00302049 could not dyn concern to custom confidence in rifle will rep TPA, check over + post at N/C #260924 </td> </tr> <tr> <td colspan="7"> THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00 </td> </tr> </tbody> </table>			Parts And Service Details	Description	Qty Needed	Warranty	Price	Disc	Amount	Serial Number: G7045179 Model: 700 RECEIVED MAR 01 2013 BY: _____							Barcode: RE00302049 could not dyn concern to custom confidence in rifle will rep TPA, check over + post at N/C #260924							THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00						
Parts And Service Details	Description	Qty Needed	Warranty	Price	Disc	Amount																								
Serial Number: G7045179 Model: 700 RECEIVED MAR 01 2013 BY: _____																														
Barcode: RE00302049 could not dyn concern to custom confidence in rifle will rep TPA, check over + post at N/C #260924																														
THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00																														

Boerner Firearms

4201 State Hwy 3 W. Ste. 111

Bremerton, WA 98312

Ph# 360.479.8056

MATTHEW R.

2/9/2013 12:39:55 PM

NATHANIEL WOOD :

REMINGTON 700 SPS 30.06SPR 27363

LOG: 201115903 SERIAL: G7045179

NATHANIEL WOOD

1303 N B ST.

360-373-1595

ABERDEEN, WA 98520

NTN # 27PX-5F8

FFL # 33272

Signature _____ 575.95

SUBTOTAL 575.95

SALES TAX 49.53

TOTAL PURCHASE 625.48

Cash 700.00

CHANGE 74.52

TRAN# 14331 STR# 001 REG# 1

THANK YOU





