.

## Remington Arms Co., Inc. Product Service Legal Case #:9200

Case Infor	mation		•						
<b>RE#</b> 321356	Date Opened 9/17/2013		<b>Opened(PS)</b> /1 <b>8</b> /2013	Date Closed 9/18/2013	Incident I	Date	Pre	Lit	Lit Obsolete
Customer	Information								
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	e Contact
Reporter	Scheels All Sports		Scheels All Spo	800 Kirkwood Mall	Bismarck	ND	58504	ł	W 701-255- 7255 F 701-258- 0245
Incident		Allen	Bovitz	9253 Hwy 24	Ft Yates	ND	58538	;	H 701-854- 4265
Incident Information									
Claims		Co	des	Repai	ir Est. Mea	lical 7	[reatm	lent	Medical Status
PI									
PD S FSR C	Cause:4006 Altered Adjustments or Components Unknown Concern:1007 Fired on Safe Release								
-	s Firearm Repai	ir form, "Gı	in has fired whe	n taking off safety	. Has happe	ened n	nore th	an or	nce." jbi
Firearm In	formation								
Mfg		Туре	Model/	Ga. SKU	J Se	rial	Bbl.		DOM

17418.	1 JPC		JIC	Octiai Doi.	DOM
Remington	CF/BA	700/243 WIN	N/A	G6606519 EC	10/16/2008 7:34:39 AM
Date Purchased	Where Purchased	Accessories	Original Owner		
	SODAK SPORT & BAIT	TWO PIECE BASE	U		
CONCERN: FSR					

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

### Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Offer to replace trigger assembly, check over, and test at 50% discount						
	Repair/Replacement Cost	Repair/Replacement Date				

9/20/13: Per Ilion, "trigger assembly set screws altered. trigger not returning properly. replace trigger assembly,

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9200&Type=... 10/1/2013

check over and test fire at 1/2 normal cost." I called Scheels and was told that I need to speak with Dallas, but that he was not there today.jbi 9/23/13: I called Scheels and spoke to Dallas about quote. He said that he will check with customer and call me back. jbi 9/30/13: Dealer sent letter to Consumer Service Rep. approving repair with credit card. jbi

### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		9/18/2013
Examination	Product Type	]	RF
	Action Type	]	Α
	Assigned To	]	S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description	]	24" 243 WIN
	Date Code	]	EC
	Bore Plugged	False	
	Bulged	False	]
Barrel	Fired	False	] .
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
<u></u>	Ext/Eject Test	False	]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9200&Type=... 10/1/2013

.

	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	]
Cafata.	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
Trianan	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components Description			TWO PIECE BASE

# Quotation

.

#### Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS. THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00321356	G	rial Number / Description 5606519 odel 700LH Center Fire Caliber: 243 WIN				Estim	Received: ate Date: Printed:	09/17/2 09/18/2 09/20/2	013
Customer:				Retu	n To:				
SCHEELS ALL SPORTS					SCHEELS ALL S	PORTS			
800 KIRKWC			800 KIRKWOOD MALL						
BISMARCK,	ND 58504	US		1	BISMARCK, NE	) 28204	05		
Please Circle One	:								
		R Card No			Exp.l	Date			
Open Account	t: R	R Card No PO Number:							
Approval Signatur	re:	Time				Date:			
If you desire any change, please use the reverse side for your comments and mark this box.					CTION				
trigger assembly s	et screws alte	ered. trigger not returning properly. replace the	rigger ass	embly,ch	eck over and test	fire at 1	1/2 normal co	ist.	
Material	Е! Туре	STIMATE (note: C.O.D./Shipping and Ha Description		harges a Qty eeded	Warranty	d in this Qty From In	Price	Disc	Amount
F305572B 4000114 4000119	Part Service Service	700 X-MARK PRO TRIG ASSB LH BLA GR-SHIPPING & HANDLING (GUN RE GR-TEST		1 1 1	Billable Billable Billable	1 1 1	86.00 17.00 23.00	0	43.00 17.00 11.50
							ub Total: Est Sales Tax	:	71.50 2.15
						(	Grand Total:		\$73.65

## SCHEELS Firearm Repair 802 Kirkwood Mall Bismarck, ND 58504 Phone 701-255-7255 • Fax 701-258-0245

ATTENTION: The estimated time on repairs is 6 to 8 weeks depending on the availability of parts needed to repair your Firearm. DO NOT leave scopes, slings, cases etc... with the firearm, they may get lost or misplaced in the shuffle.

	9200 DATE <u>4-9</u> 20 13					
HOME PHONE (701) 854-4265	S OTHER PHONE					
CUSTOMER NAME Allen Bouitz	ADDRESS 9253 Hwy 24					
CITY FF Yates STATE R MAKE Remination MODEL 700	58538					
serial NO. <u>66606519</u>	INSURANCE VALUE 750					
CUSTOMER SIGNATURE	over					
	2SERVICETO BEDONE					
Gun Has Fired	when taking off Safety.					
Hos Hoppined More	than once.					
BG6606519						
Model: 700	F					
	USE ONLY					
	SHIPPED BY					
RE00321356	DECEIVE					
KE00321330	I SEP 2 0 2013					
COMPANY NAME Reminition Direct	ADDRESS					
CITY STATE	ZIP Y:					
DATE RETURNED 2	20					
CUSTOMER CONTACTED						
	AMOUNT DUE \$					
and the second state of the second state and the second state of t						
COMMENTS	ON REPAIR STATUS					
	T.A. set screws oft Trig. Not al property. Mg.					
	TOD A GUL AND TOUT					
	AT 1/2 NORW. COST.					
	Q					

WHITE - FILE YELLOW - ACCOMPANIES FIREARM PINK - CUSTOMER COPY

24

xc10/0

002291







