PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8209

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 291908
 12/7/2012
 11/27/2012
 1/7/2013
 11/26/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident John Kowalsky 165 South Opdyke, Lot 133 Auburn Hills MI 48326 H 216-659-1332

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

Pl ringing ears

PD hole in new pool table, set of patio doors

Cause:4015 Improper Maintenance Concern:1020 Fired on Bolt Opening

U

S

C

11/27/12 Per call from John, when coming back in from hunting Sunday morning they all laid their rifles on the pool table. He had a round in his rifle and picked it up and when he lifted the bolt to eject it fired. It shot a hole in a new pool table and damaged a set of patio doors. He has had it for a while and it worked fine. He inherited the rifle. 3 people have ringing ears from this incident.cm

Firearm Information

SKU Model/Ga. DOM Mfg. Type Serial Bbl. CF/BA 700/7MM REM MA n/a 153275 5/1/1965 Remington KM Where Purchased Original Owner Accessories

Date Purchased Where Purchased Accessories Original Owner

CONCERN: FIRED LIFTING BOLT

Ammunition Information - None Defined Other Products Information - None Defined

Remington/700/CF/BA

Scttlement Release of Claims Release Date Reimbursement Cash Reim. Cash Date APV APV

Replace TPA no charge as goodwill

Settlement

Repair/Replacement Cost Repair/Replacement Date

11/27/12 Sending box from Ilion and ARS from NC.cm 1/4/13 Left voice msge for Kowalsky that trigger was rusty and dirty and that was the cause of the follow down of the trigger. We can clean, replace TPA no charge as goodwill but will not cover PI/PD. This was from maintenance not a defect from the factory.cm 1/7/13 Voice message from Kowalsky stated he was ok with the replacement TPA and repairs. He asked if he could get the old trigger back also to see it. I will call him and let him know that we don't send back the parts that are out of spec.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
	4015	Improper Maintenance	
	Description		24" 7MM REM MAG
	Date Code		KM
	Bore Plugged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8209&Type=Case

1/7/2013

PrintDisplay Page 2 of 2

Barrel	Bulged	False	<u> </u>
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Šelect	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	1
Receiver	Condition	Slightly Worn; Functioning	
Keceivei	Bulged	False	
Safety	Description]	BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
Sear	Lift	Select	.001
	Notch	Slightly Worn; Functioning	O/S DOUBLE SEAR
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY WILL FOLLOW DOWN ON SAFETY NULL TEST
	Pul1	Select	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

November 27, 2012

John Kowalsky 165 South Opdyke Lot 133 Auburn Hills, MI 48326

Subject: Case # 8209, Model 700, SR #36518

Dear Mr. Kowalsky,

Enclosed in this letter is a UPS ground prepaid shipping label to cover shipment of the firearm to Remington for inspection. Please include the "Service Request" and a copy of this letter inside with the firearm. The Service Request inside is important as sometimes the outside label gets damaged in transit and we want to be sure the product is logged in correctly. Please mark the small ends of the boxes "Product Service.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

153275.

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service



Mádison, NC 27025-0700


ATTN: Prod Serv #8209


Parts and Repairs: P:800-243-9700/F:336-548-7801


www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Sefvice Request Number Serial Number Description			Date of Request:	11/27/2012
SR00036518	153275	•	Date Printed	: 11/27/2012
Customer: JOHN KOWALSKY		Destination: Arms Services		
165 SOUTH OPDYKE	LOT 133	I4 Hoefler Ave		
AUBURN HILLS, MI		Ilien, NY 13357	US	
Email:		Email:		
Your request for service on the returned. If not, you will be co	item(s) will be evaluated by our repairman to determ ntacted with an estimate before work is performed.	ine if it is covered under our warranty pol	icy. If it is your firca	m will be repaired and
		* :*		
			:	,
Reason For Return Se M123 - FORWARD TO F	RODUCT SERVICE FOR INSPECTION			The second second
Service Request Section				
Prod Scrv #8209		arting the state of the state o	the state of the s	آچيسند الفاقه <u>دين خون د</u> ده <u>فقت ته استان دانيات کا دنيان تا</u>
Parts And Service Details Material Type	Description	Qty Warranty Needed	Price	Disc Amount
	•			
				i
				İ
				;
THIS IS NOT AN INVOICE. T being sent based on the conven	This is a pre-estimate to repair, recondition, or replace sation with our representative.	the item(s)	Sub Total: Est Sales Ta	x: .00
			Grand Total	: \$.00









ARS LABEL REQUEST FORM

11/27/2012	Service Request #	SR00036518	
1	WEIGHT PER PACKAGE:	10 LBS	
mitchelles	email address:	4	
	4		
	1	1 WEIGHT PER PACKAGE:	1 WEIGHT PER PACKAGE: 10 LBS

Business:

Remington Service
PO Box 700
Madison, NC 27025-0700
www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

JOHN KOWALSKY 165 SOUTH OPDYKE LOT 133 AUBURN HILLS, MI 48326 US SR00036518

Email:

RETURN ITEM TO:

ILN

Arms Services



1

4XX596 NOV 28, 2012 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS TRACK ING# 1Z4XX5969065733518

REF 1:SR00036518

REF 2:

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50

DV 0.00 DGD 0.00 SD 0.00

QH 0.00 PR 0.00 SP 0.00

JOT PUB CHG 9.69 PUB+HANDLING 9.69

ATTN: Prod Serv #8209

PS 32763



