Remington Arms Co., Inc. Product Service Legal Case #:9355

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 328044
 11/19/2013
 10/25/2013
 11/20/2013
 10/24/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident John Marge 277 Rt. 20 Chester MA 01011 H 413-354-6330

PO Box 683

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern

Unknown

S FSR C

Concern:1007 Fired on Safe Release

O'MOIOWII

Reim.

Cash

10/25/13: Customer called in. He said he bought gun used. He stated he used it on 10/24/13 and it fired on safe release. Customer stated he read on the internet about thousands of Model 700's with issues like his. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/270 WIN
 n/a
 6863120 KZ 5/1/1975

Date Purchased Where Purchased Accessories Original Owner

CAMFOUR INC WESTFIELD MASS N

CONCERN: FSR

Ammunition Information - None Defined
Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Date APV APV

Per Ilion -Quote to repair under BLM

Repair/Replacement Cost Repair/Replacement Date

\$29

10/28/13: Mailed ARS, letter, SR paperwork. Box order# 1556017. df 11/22/13: Per Ilion - Could not duplicate concern. Replace TA, check over & test under BLM - quote. df 12/3/13: I called cust. & left VM requesting a call back about quote. Customer called back & said he mailed the quote w/payment just before Thanksgiving. Payment received & applied. df

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9355&Type=... 12/3/2013

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/20/2013
	Product Type		RF
	Action Type		A
	Assigned To	· ·	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		KZ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	Ī
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
0.0.	Description		BOLT OOCK SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.008
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	7#
Trigger	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9355&Type=... 12/3/2013

Quotation

Remington Service

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00328044		Serial Number / Description 6863120 Model 700 Center Fire Calib				Date Re Estimate Date Pri	e Date:	11/18/2 11/21/2 12/02/2	013
Customer: JOHN MARC 277 RT. 20 CHESTER, 1		US]	rn To: IOHN MARGE 277 RT. 20 CHESTER, MA		3		
Please Circle One	:					 			
VISA MC	DISCOV	/ER Card No F			Exp	Date	·		
Open Accoun	t: R	F	O Number:						
Approval Signatu	re:					_ Date:			
)							
Reported		ge, please use the reverse side	Pro	s and mark this beblems Found M123 - FORV			VICE FOR	INSPE	CTIÓN
				Comments					
could not duplica	te concern.	replace trigger assembly, chec	k over and test fire	e under bolt lock	program for \$2	0.00 + shipp	ing		
		ESTIMATE (note: C.O.D./S	Shipping and Hon	dling Charges a	re NOT Includ	ad in this O	nota)		
Material	Type	Description		Qty Needed	Warranty	Qty From Inv	Price		Amount
F305570B	Part	X-MARK PRO 700 TRI			Warranty	1	.00	0	.00
4000114	Service	GR-SHIPPING & HANI	DLING (GUN REI	•	Billable	1	17.00		17.00
4000116	Service	GR-LABOR		20	Billable	20	1.00	0	20.00
4000119	Service	GR-TEST		1	Warranty	1	.00	0	.00
			. (:	2/3/13 Paid	df		·		
						Est	o Total: Sales Tax: and Total:		37.00 .00 \$37.00

emington. Copy

October 28, 2013

John Marge 277 Rt. 20 PO Box 683 Chester, MA 01011 Phone: 413-354-6330

Ref # 9355, Model 00, Serial # 6863120

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. A rifle box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

> Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co, LLC Phone: 1-800-243-9700 ext 8686

Fax: 336-548-7872

£6863120 Model:

could not dep coorenn Mr. T.A. check over t pest and Bir Roz 70 +

Q

Service Request

Remington Service

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description 10/28/2013 Date of Request: SR00065626 6863120 Date Printed: 10/28/2013 Model 700 Center Fire Caliber: 270 Customer: JOHN MARGE Destination: Arms Services 277 RT. 20 14 Hoefler Ave CHESTER, MA 01011 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 9355 - Customer stated rifle fired on safety release. df Parts And Service Details Material Type Description Qty Needed Warranty Price Disc Amount THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) .00 Sub Total: being sent based on the conversation with our representative. Est Sales Tax: .00 **Grand Total:** \$.00

Model Number:	Serial Number:	Serial Number:			
700	6863120				
Name:	Date of Purchase:				
John T. Marge					
Address (no PO Boxes):					
277 Rt. 20					
City: Chester	State: MA	Zip: 0/0//:			
Phone (Daytime):	Fax:				
413 3546330	rdx.				
E-mail Address:					
Please describe your problem Rifle fired wh the fire position	The second secon	s put in			
500 characters left NOTE: Prior to shipping your fire	arm, contact the Repa	ir Center for services			
provided and estimated repair til	116:-				

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a

firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post: Remingtorris not responsible for damage or loss—

during shipment, so you may elect to purchase insurance from your carrier.

use our UPS label

www.remington.com/en/pages/support/general-repair-form.aspx

ARS LABEL REQUEST FORM

DATE:	10/28/2013	Service Request #	SR00065626	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY: fulcherdm		email address:	I WILL MAIL LABEL	

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

JOHN MARGE

277 RT. 20 PO Box 683 CHESTER, MA 01011 US SR00065626

Email:

RETURN ITEM TO:

ILN

Arms Services



4XX596 OCT 28, 2013 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS TRACKING# 124XX5969066653068 REF 1:SR00065626 1 OF 1

HANDLING CHARGE 0.00 SVC T/P USD RS 0.50 SD 0.00 SP 0.00 HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS:
DV 0.00 COD 0.00

DC 0.00 DGD 0.00

AH 0.00 PR 0.00

TOT PUB CHG 9.00 PUB+H PUB+HANDLING

ATTN: Product Service

ARS LABEL REQUEST FORM

DATE:	11/08/2013	Service Request #	SR00065626
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

JOHN MARGE

277 RT. 20 PO Box 683 CHESTER, MA 01011 US

SR00065626

Email:

RETURN ITEM TO:

ILN

Arms Services



and mo

4XX596 NOV 8, 2013 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS TRACKING# 124XX5969066937967 1 OF 1 REF 1:SR00065626

TOT PUB CHG 9.00

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS:
DV 0.00 COD 0.0
DC 0.00 DGD 0.0
AH 0.00 PR 0.0 SVC T/P USD RS 0.50 SD 0.00 0.00 0.00 SP 0.00 9.00 0.00

PUB+HANDLING

ATTN: Product Service







