Page 1 of 2 PrintDisplay

> Remington Arms Co., Inc. Product Service

Legal Case #:8647 Case Information Date Opened(PS) **Date Closed** RE# Date Opened Incident Date Pre Lit Lit Obsolete 2/18/2013 2/25/2013 2/25/2013 301084 Customer Information First State Zip Age Type Business Last Name Street City Contact Name W 513-422-4191 Roberson Sporting Roberson 6348 Germantown Middletown OH 45042 Reporter E Rd Sporti Goods robersonsporting@sbcglobal.net Incident Information Repair Est. Medical Treatment Medical Status Claims Codes Ρį PD Cause: 4015 Improper Maintenance Unknown Will fire when the safety is moved Concern: 1007 Fired on Safe Release 2/28/13 Per note on SR, dealer said the rifle will fire when the safety is moved.cm Firearm Information Mfg. Type Model/Ga. SKU Serial Bbl. DOM G6308484 CX 4/3/2003 2:39:39 PM Remington CF/BA 700/300 SAVAGE 25869 Date Purchased Where Purchased Accessories **Original Owner** AMERICAN ROD & GUN TWO PIECE BASE U CONCERN: FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Settlement Date APV Per Ilion, offer to replace TPA, clean and test fire at 1/2 normal cost Repair/Replacement Repair/Replacement Cost Date 2/28/13 Per Ilion, trigger and trigger pin rusted and is binding trigger. Can offer to replace TPA, clean and test fire at 1/2 normal cost.cm Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/25/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Вапе!	Description		24" 300 \$AVAGE
	Date Code		CX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
		<u> </u>	 1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8647&Type=Case

2/28/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	F.E TIP DAMAGED & SMALL CRACK
n. * .	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning]
Receiver Safety	Bulged	False]
	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG,TRIG PIN RUSTED
	Puli	Select	10+#
Trigger	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description]	TWO PIECE BASE

Service Request

WITH YOUR RETURN.

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT 1014

Service Request Number SR00044427	Serial Number / Description G6308484	8642	Date of Request: 02/06/2013 Date Printed: 02/08/2013	
Model 700 RIFLE Caliber: 300 Customer: ROBERSON SPORTING GOODS 6348 GERMANTOWN RD MIDDLETOWN, OH 45042 US Email: robersonsporting@sbcglobal.net		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US		
		Email:		
	e item(s) will be evaluated by our repairman to dete ontacted with an estimate before work is performed		olicy. If it is your firearm will be repaired and	
Reason For Return	-			
м995 - SAFETY			· No National Automotives	
Service Request Section	LE WILL FIRE WHEN THE SAFETY IS MO			
Clerk CW Customer Name Address	Date 2 13 13 Date 2 13 13 Liming Frn Direct		Deceive	
h 0			₩ FEB 2 6 2013 ₩	
he: kimingt Derinzut	M. 760 + G6308414	TRIO + TI	ng. PIN rushed + 15	
PING PAIL	Should WDA	SINKING	TOIQ CANOFILK &	
	Should your Questions	Mp. TOF	Nonwal cost.	
G6308	484		Q	
Model: 70		(Fle tip	damaged & consciled)	
	00301084	ю item(s)	Sub Total: .00 Est Sales Tax: .00	







