

Remington Arms Co., Inc.
Product Service
Legal Case #:8564

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
299055	2/1/2013	2/4/2013	2/4/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Leo	Sanchez	319 South 3rd Street	Bay Town	TX	77520		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		Unknown
S	Fires when taking off safety	Concern:1007 Fired on Safe Release		
C				

2/20/13 Per note on SR, as soon as the firearm is taken off of safety the gun fires without pulling the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	25783	F6248174	XW	1/6/2003 8:05:22 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test at 1/2 normal cost	Repair/Replacement Cost	Repair/Replacement Date				

2/20/13 Per Ilion, trigger is rusted to sideplates and not moving. Replace TPA, clean and test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/4/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
	Description		24" 22-250 REM
	Date Code		XW

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG RUSTED TO SIDEPLATES WILL NOT MOVE, WILL FOLLOW DOWN
	Pull	--Select--	N/A
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

2411
XW12/1
100'

Service Request Number SR00037694	Serial Number / Description F6248174 Model 700 RIFLE	Date of Request: 12/06/2012 Date Printed: 12/06/2012
Customer: LEO SANCHEZ 319 SOUTH 3RD STREET BAY TOWN, TX 77520 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US	
Email:	Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M993 - AS SOON AS SAFETY RELEASED GUN FIRES

Service Request Section
AS SOON AS FIREARM IS TAKEN OFF OF SAFETY, GUN FIRES WITHOUT PULLING TRIGGER.

Serial Number: F6248174

Model: 700



RE00299055

Qty Needed	Warranty	Price	Disc	Amount
------------	----------	-------	------	--------

RECEIVED
FEB 05 2013

BY:

Trig. is rusted to side plates + not moving. Rep. TBA, clean + test at 1/2 normal cost.

Q

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00

...WHERE YOUR GREAT OUTDOORS BEGINS...

CARTER'S COUNTRY

INVOICE 100 0

☐ 8231 TREASCHWIG * SPRING, TX 77373 * (281) 443-8393

☒ 2120 SHAVER * PASADENA, TX 77502 * (713) 475-2222

☐ 8927 KATY FREEWAY * HOUSTON, TX 77024 * (713) 481-1844

☐ 11886 WILCREST * HOUSTON, TX 77031 * (281) 878-1466

DATE: 1/5 2012

Name LEOBARDO SANCHEZ

NICS #:

Address 319 SOUTH THIRD ST

CHL #:

Exp. Date:

City BAYTOWNState TEXASZip 77520TXDL #: 05827869

Cell #:

Home #:

Work #:

Exp. Date:

DOB:

SOLD BY		RUNG BY		CASH	CHECK	VISA/MC	AMEX	DISCOVER	FINANCE COMPANY		TX EXEMPT - PURCHASER	
K9												
QUANTITY	MFR - MODEL		CAL / PWR		SERIAL #		CONTROL #		PRICE		AMOUNT	
1	REMINGTON 700 BDL		22-250		F6348174		DATE OF PURCHASE		9/18/2004			
							Duplicate Receipt				15.00	
							Text					
							Total					
<i>Customs of Records</i> <i>Sandy Delgado 281-821-0070</i>												
	NEW#	NEW#	NEW#		NEW#	OLD#						
MFR					MFR			TRADE-IN				
TYPE					POWER			PURCHASE				
MODEL					SERIAL#			RTS				
ACTION					MODEL			LAW RTS				
CAL/GA					REASON RTD							
SERIAL#												
	OLD#	OLD#	OLD#									
CREDIT OR AMOUNT PAID				CUSTOMER SIGNATURE								
MARKED PRICE				Email Address								

LIMITED WARRANTY - ALL MERCHANDISE WARRANTED BY MANUFACTURERS
 10% RESTOCKING CHARGE ON AUTHORIZED RETURNS. NO RETURNS AFTER USE, WITHOUT RECEIPT OR AFTER 30 DAYS. NO CASH REFUNDS AFTER 14 DAYS.
 THANK YOU - PLEASE KEEP THIS COPY FOR REFERENCE.





