#### Remington Arms Co., Inc. Product Service Legal Case #:9449

				Legur Oude and and						
Case Info	rmation									
RE#	Date O	pened Da	ate Opened(PS	5) Date Closed	l Inci	dent Da	te P	re Lit	Lit	Obsolete
330172	12/9/2	2013	11/11/2013	12/10/2013						
Customer	Informatio	on								
Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Co	ntact
Incident		Chris	Schottel	16611 6400 Rd	Montros	e CO	81403	H	H 970-	901-7051
Incident I	nformation	1								
Claims		(	Codes	Rep	air Est.	Medica	l Treat	ment	Medic	al Status
PI										
PD	Cause	:4038 Coul	d Not Duplicat	e Concern		T 1	.1			
S FBC	Conce	rn:1008 Fired	on Bolt Closin	ng		Ur	iknowr	l		
С										
11/11/13:	I received	call from Chr	is Schottel, he	said that his gun h	as fired or	n bolt clo	osing o	n 2 diffe	rent oc	casions.
jbi				U			2			
Firearm I	nformation	1								
Mfg	g.	T	ype	Model/Ga	ı <b>.</b>	SKU		Serial	Bbl.	DOM
Remin	gton	CF	/BA	700/7MM W MA	BY	25909	C	665077	6 KL	5/10/1991
Dat	e	Where <b>P</b>	urchased	Accessorie	es	Origina	al			

Date Purchased

Where Purchased SERVISTAR / COAST TO COAST

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined Settlement

Remington/700/CF/BA

Owner

Y

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace trigger, check over, and test at 50% discount						
	Repair/Replacement Cost	Repair/Replacement Date				
	ARS, letter, and SR pape					

not duplicate concern. To restore confidence in rifle can offer to replace trigger assembly, check over and test fire at 1/2 normal cost." jbi 12/12/13: I called Chris Schottel, he approved quote with a credit card. jbi

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9449&Type... 12/12/2013

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/10/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To	ĺ	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM WBY MAG
	Date Code		KL
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed	<u></u>	•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
-	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	FINISH WEAR
Overall	Stock Condition	Worn; Functioning	FINISH WEAR,SCRATCHES,MARS,DENTS
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
~ ^	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.015
Sear	Notch	Slightly Worn; Functioning	
	<u> </u>	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	3#
Trigger	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9449&Type... 12/12/2013

Ŀ

.....t

.

\_\_\_\_

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9449&Type... 12/12/2013

## Quotation

.

•

#### Remington Service PO Box 700

Madison, NC 27025-0700

www.Remington.com

### Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number Serial Number / Description   RE00330172 C6650776   Model 700 Center Fire Caliber: 7 MM WEATHERBY MAG				Date Re Estimat Date Pr	e Date:	12/09/2 12/10/2 12/11/2	013		
Customer:	- <b></b>			Retu	irn To:	<b>C1</b>			
CHRIS SCHOTTEL 16611 6400 RD MONTROSE, CO 81403 US				CHRIS SCHOTTEL 16611 6400 RD Montrose, co 81403 US					
Please Circle One									
VISA MC	DISCOV	'ER Card No PO Num			Exp.I	Date			
Open Account	IC K		luci						,
Approval Signatu	ıre:		<u></u>			Date:			<u>.</u>
		)							<del></del>
If you desir	e any chang	ge, please use the reverse side for you	r comments and m Problems	ark this t	00X.				
Reported M123 - FORW	ARD TO P	RODUCT SERVICE FOR INSPECT	Found		WARD TO PROD	UCT SER	VICE FOR	INSPE	CTION
			Technician Comm					·····	
could not duplica	ite concern.	to restore confidence in rifle can offe	er to replace trigge	r assemb	ly, check over and	test fire at	1/2 normal	l cost.	
		ESTIMATE (note: C.O.D./Shippin	g and Handling C	harges			uote.)		
Material	Туре	Description	r	Qty Needed	Warranty I	Qty From Inv	Price	Disc	Amount
F305570B 4000114 4000119	Part Service Service	X-MARK PRO 700 TRIG ASSI GR-SHIPPING & HANDLING GR-TEST		i) 1 1 1	Billable Billable Billable	1 1 1	97.00 17.00 23.00	0	48.50 17.00 11.50
							b Total: Sales Tax	-	77.00 1.46
								•	
						Gr	and Total:		\$78.46



24" 1LLS/C

November 11, 2013 9442

Chris Schottel 16611 6400 Rd Montrose, CO 81403 Phone: 970-901-7051


Ref # 9449, Model 700, Serial # C6650776

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I hope that this action will keep you a loyal Remington customer.

Sincerely, J.B. Irving Consumer Affairs Administrator Remington Arms Co, LLC / H&R Phone: 336-548-8684 Fax: 336-548-7872



BY:-----

Q

BC6650776 Model: ΕØ N 330

could not dyp. Loncepn. To restone conf. in Rifle CAN olther to rup: T.A. elucicover + Test AT 1/2 Noitural Lost

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

# Service Request

•

.

Remington Service PO Box 700

ATTN: Product Service

Madison, NC 27025-0700

### www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00067180 Customer: CHRIS SCHOTTEL 16611 6400 RD MONTROSE, CO 814 Email: Your request for service on th returned. If not, you will be co	Serial Number / Description C6650776 Model 700 RIFLE 403 US e item(s) will be evaluated by our repairman to determ untacted with an estimate before work is performed.	Destination: Arms Servic 14 Hoefler A Ilion, NY 1 Email: ine if it is covered under our warra	es Ave 3357 US	11/11/2013 11/11/2013 n will be repaired and
<b>Reason For Return</b> M123 - FORWARD TO	PRODUCT SERVICE FOR INSPECTION			
Service Request Section Product Service #9449. jbi				
Parts And Service Details Material Type	B Description	Qty Warrant Needed	y Price	Disc Amount
	This is a pre-estimate to repair, recondition, or replace	the item(s)	Sub Total:	
being sent based on the conver	satton with our representative.		Est Sales Tax Grand Total:	

## ARS LABEL REQUEST FORM

.

DATE:	11/11/2013		Service Request #	SR00067180
QUANTITY:	1		WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	irvingjb		email address:	I will mail
Business:		Remington Servi PO Box 700 Madison, NC 27 www.Remington	025-0700	
		LABEL IN	FORMATION	
MAIL LABE	EL TO:	CHRIS SCHOTT 16611 6400 RD MONTROSE, C SR00067180		
		Email:		
RETURNI	TEM TO:	ILN Arms Services		
				CURR USD t OF 1 LBS
ATTN: Pro	duct Service	HANDLI Single DV 0.0 DC 0.0 AH 0.0	) DGD 0.00 ) PR 0.00	SVC T/P USD RS 0.50 SD 0.00 SP 0.00 ANDLING 12.98

PS 33771



