

Remington Arms Co., Inc.
Product Service
Legal Case #:8471

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
296328	1/11/2013	1/14/2013	1/14/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Bill	Schwarzkopf	552 north 15th Ave	Forsyth	Mt	59327		E bschwarzkopf@mt.gov

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when safety removed	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release	Unknown	
C				

1/18/13 Per note on SR, accidental discharge when safety removed, gun was in vice. Complete Safety Modification Program.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	6580839	WW	8/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILLINGS HDWE BILLINGS MONT		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Remington/700/CF/BA						
Repair/Replacement Cost	Repair/Replacement Date					

1/18/13 Per Ilion, could not duplicate concern. Trigger assm dirty, parts work sluggish. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/14/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN

Barrel	Date Code		WW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY. PARTS WORK SLUGGISH
	Pull	---Select---	8#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P.800-243-9700 F.356-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the information will serve as a guideline for our Service Department to address your specific concerns and provide you with

THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00038683
Serial Number / Description 6580839

8471

Customer:
BILL SCHWARZKOPF
552 NORTH 15TH AVE
FORSYTH, MT 59327 US

Destination:
Custom Gun S
14 Hoefer Ave
Ilion, NY 133

Email: bschwarzkopf@mt.gov

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M140 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
Accidental discharge when safety removed gun was in vice complete Safety Modification Program

Qty. needed Warranty

Stamp: BILL F. SCHWARZKOPF, 401 N. 15TH AVE, FORSYTH, MT 59327
Signature: Roger Vira
Signature: Bill Schwarzkopf
Stamp: FIRST STATE BANK OF MONTANA, 100 N. 15TH AVE, FORSYTH, MT 59327
FOR 370 rifle
1908 \$400.00 10/14/2009

RECEIVED
JAN 15 2013
BY:.....

could not dep. concern
T.A. dirty, parts work
Sluggish, Rep. T.A. clean
Test u.d. SLP Con 20.7

Serial Number: 6580839
Model: 700



RE00296328





