

Remington Arms Co., Inc.
Product Service
Legal Case #:9158

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 319582 | 8/30/2013 | 9/4/2013 | 9/4/2013 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|------------------------|------------|-----------------|------------------|----------------|-------|-------|-----|----------------|
| Reporter | Tri-County Sports Shop | | Tri-County Spor | 89 Grandview Ave | Point Pleasant | WV | 25550 | | W 304-675-2988 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|------------|------------------------------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4006 | Altered Adjustments or Components | | |
| S | FBC | Concern:1008 Fired on Bolt Closing | Unknown | |
| C | | | | |

Per note from Tri-County Sport Shop, "customer states gun will go off when shoving bolt forward about once or twice every 8-9 shots. Please repair. Call customer for prices. Alfred Fauver - 304-593-4431." jbi

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|-----------------------------|-------------|----------------|---------|------|----------|
| Remington | CF/BA | 700/222 REM | N/A | 6547932 | BX | 1/1/1975 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | BLUEFIELD SP BLUEFIELD W VA | | U | | | |

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace trigger assembly under BLP for \$20.00 + shipping and repair magazine at 50% discount | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |
| | \$24 | | | | | |

9/5/13: Per Ilion, "trigger assembly dirty and sticky. set screws altered. magazine assembly missassm and mag spring damaged. replace trigger assembly under bolt lock program for \$20.00 and repair magazine assm at 1/2 normal cost. test fire." jbi 9/6/13: I called customer, Alfred Fauver, he approved quote with credit card. jbi

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace trigger assembly under BLP for \$20.00 + shipping and repair magazine at 50% discount | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |
| | \$24 | | | | | |

9/5/13: Per Ilion, "trigger assembly dirty and sticky. set screws altered. magazine assembly missassm and mag spring damaged. replace trigger assembly under bolt lock program for \$20.00 and repair magazine assm at 1/2 normal cost. test fire." jbi

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|------------------------|-----------------------------------|----------------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 9/4/2013 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | S.NICHOLS |
| Cause | 4006 | Altered Adjustments or Components | IMPROPER MAINTENENCE |
| Barrel | Description | | 24" 222 REM |
| | Date Code | | BX |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Not Functioning | BINDS |
| | Condition | Slightly Worn; Functioning | |

| | | | |
|--------------|--------------------|--------------------------------|---|
| Extractor | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Not Functioning | |
| | Stock Condition | Slightly Worn; Functioning | MARS,SCRATCHES |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | ---Select--- | .005 |
| | Notch | Slightly Worn; Functioning | |
| | | Test Fired | False |
| Feeding Test | Tests | False | |
| Trigger | Condition | Slightly Worn; Not Functioning | DIRTY,STICKY TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN |
| | Pull | ---Select--- | 2.5# |
| | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Bolt Lock | |

Quotation

Remington Service

PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

| | | |
|----------------------|--|-----------------------|
| Repair Number | Serial Number / Description | Date Received: |
| RE00319582 | 6547932 | 08/30/2013 |
| | Model 700 Center Fire Caliber: 222 REM | Estimate Date: |
| | | 09/04/2013 |
| | | Date Printed: |
| | | 09/06/2013 |

Customer:

TRI COUNTY SPORTS SHOP
89 GRANDVIEW AVE
POINT PLEASANT, WV 25550 US

Return To:

TRI COUNTY SPORTS SHOP
89 GRANDVIEW AVE
POINT PLEASANT, WV 25550 US

Please Circle One:

VISA MC DISCOVER Card No. _____ Exp.Date _____

Open Account: R _____ PO Number: _____

Approval Signature: _____ Date: _____

Daytime Phone: (_____) _____ Time to Call: _____

☐ If you desire any change, please use the reverse side for your comments and mark this box.

Problems

Reported

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION
M240 - BOLT LOCK SAFETY MODIFICATION

Found

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION
M240 - BOLT LOCK SAFETY MODIFICATION

Technician Comments

trigger assembly dirty and sticky.set screws altered.magazine assembly missassm and mag spring damaged.replace trigger assembly under bolt lock program for \$20.00 and repair magazine assm at 1/2 normal cost. test fire

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)

| Material | Type | Description | Qty Needed | Warranty | Qty From Inv | Price | Disc | Amount |
|----------|---------|--|------------|----------|--------------|-------|------|--------|
| F305570B | Part | X-MARK PRO 700 TRIG ASSB RH BLACK (OS) | 1 | Warranty | 1 | .00 | 0 | .00 |
| F91133 | Part | 700 MAG SPRING (222;17;223) | 1 | Billable | 1 | 7.00 | 50 | 3.50 |
| 4000114 | Service | GR-SHIPING & HANDLING (GUN REPAIR) | 1 | Billable | 1 | 17.00 | 0 | 17.00 |
| 4000116 | Service | GR-LABOR | 20 | Billable | 20 | 1.00 | 0 | 20.00 |
| 4000119 | Service | GR-TEST | 1 | Warranty | 1 | .00 | 0 | .00 |

Sub Total: 40.50

Est Sales Tax: 2.43

Grand Total: \$42.93

**TRI-COUNTY SPORTS SHOP****GUNS & RELOADING SUPPLIES**89 Grandview Avenue
Point Pleasant, WV 25550

(304) 675-2988 Fax (304)-430-3415

www.tcsportshop.com

9158

24"
B+1/2"
2.54
.005

| | | | | | |
|--|---------------|--------|--------|----------|--------------|
| CUSTOMER'S ORDER NO. | | PHONE | | DATE | |
| | | | | 8/24/13 | |
| NAME ILION FIREARMS PLANT | | | | | |
| ADDRESS 14 HOEFLER AVE. ILION, NY 13357 | | | | | |
| SOLD BY | CASH | C.O.D. | CHARGE | ON ACCT. | MDSE. RET'D. |
| | | | | | |
| QTY. | DESCRIPTION | | | PRICE | AMOUNT |
| | Remington 700 | | | | |
| | 222 Rem | | | | |
| | S/N - 6547932 | | | | |
| customer states gun will go off when shoving bolt forward also about once or twice every 8-9 shots. Please Repair Call customer for Prices ALFRED FAUVER-304-593-4431 REF# SR58957 Thank You! | | | | | |
| RECEIVED BY | | | | TAX | |
| | | | | TOTAL | |

RECEIVED
SEP 05 2013

BY:.....

C PRODUCT 610

All claims and returned goods must be accompanied by this bill.

1975

Thank You

Serial
Number:

6547932

Model: 700



RE00319582

T.A. dirty + sticky, set screws
Altered mag. ASSM MRC ASSM
+ mag. spr. damaged. Rep. TPA
and BLP for 20 +. rep. mag.
spr, check over + test,

Q











