PrintDisplay

,*

•

					-	on Arms Co., In duct Service	IC.						
					Lega	l Case #:8456							
Case Infor	mation												
RE# 295578		Opened 9/2013	I	Date Opened 1/10/2013	• •	Date Closed 1/10/2013	Inc	ident D	ate	Pre	Lit	Lit	Obsolete
Customer	Information	1											
Туре	Business	First Na	me I	Last Name	Stree	t Cit	y Sta	ite Zi	p Ag	e		Conta	ict
Incident		Randy	, · ·	Yarbrough	713 S. Hig	gh St Winch	ester TI	N 373	98	F			8-1879 yahoo.com
Incident In	formation												
	Claims			1	Codes		Repa	air Est.	Medi	cal Tr	eatmen	t M	edical Status
PI													
PD		(Cause:4(006 Altered	l Adjustmen	ts or Componen	ts		,	Unkno	1.1.11		
S Fired	when closii	ng bolt (Concern	:1008 Fired o	n Bolt Closi	ng			•		wn		
-	r letter with	rifle on Su	undav m	orning (letter	dated 12/30	/12) his son and	he were h	unting a	nd load	ed the	rifle as	alway	when he
						oth safety on and			101010		nne as	anay	s. when he
									·				=- ·
Firearm In	formation												
Mf	g.	Туре			Мос	lel/Ga.			SKU		Seria	I B	bl. DOM
Remin	•	CF/BA				WIN MA		-	26973		D62182	250 H	KP 5/4/1995
Date Pur	chased	Where Pur				ssories		Origi	nal Ow	ner			
CONCERN	LECD	BANGER	SLP	TWO PI	ECE BASE,I	RINGS, AFT ME	CT STK		U				
CONCER	N:PSK												
Ammuniti	on Informat	tion - None	Defined										
		nation - Nor											
Settlement		1441011 - 1401	ie Derm	22									
Demoniciii					Reming	gton/700/CF/BA							
5	Settlement		Relea	se of Claims	Re	lease Date	Reimbur	sement		esh ement		n. Date PV	e Cash Date APV
	PA, clean a 2 normal co								ocial	ment	А	ж ¥	AI ¥
			Repair	/Replacemei Cost	nt Repair	r/Replacement Date							
1/17/13 Pe	r Ilion, trig	ger assm di	rty and s	sticky. Set scr	ews altered.	Replace TPA, c	lean and te	est at 1/2	normal	cost.c	m		
,													

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENANCE
Barrel	Description		24" 338 WIN MAG AFT MKT MUZZLE BREAK
	Date Code		КР
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

1/17/2013

í

÷

;

٠

.

L	Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Select	AFT MKT
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Lift	Select	.013
Scar	Notch	Slightly Worn; Functioning	· ·
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY, STICKY.BOLT STOP AND SEAR WORK SLUGGISH
Trigger	Pull	Select	4#
~~	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, RINGS, AFT MKT STK

1/17/2013

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

.

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCI YOUR RETURN.

Service Roquer Numberial Number / Description SR00040094 D6218250	Date of Request\$1/02/2013 Date Printed\$1/02/2013
Model 700DM RIFLE Caliber: 338 RANDY YARBROUGH 713 S. HIGH STREET WINCHESTER, TN 37398 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US
Email: ryarchery@yahoo.com	Email:
Your request for service on the item(s) will be evaluated by our repairm returned. If not, you will be contacted with an estimate before work is p	nan to determine if it is covered under our warranty policy. If it is your firean performed.
Reason For Return M295 - EVALUATE AND REPAIR/SAFETY INSP. M992 - FIRES/SAFE	
Service Request Section gun fires on safe	
Parts And Service Details Material Type Description	Qty Warranty Price Disc Amount Needed
D6218250	
	JAN 1 4 2013
RE002955/8	BY:
	T.A. dinty + Sticky. Set screw. pltered. Rup Wace TPA, cleak
	4 TOST AT 1/2 MOROMALEUST, Q Sub Total: .00
	Est Sales Tax: .00 Grand Total: \$.00

12/30/2012 is Kandle Garberryh nchester, Tr. ajk 5 hone 931-30 Keme Mag Sunday Making My Son & 11 ero Allukijs Safta on the outen zecal <u>\$ 7</u> Kemington ALL My Life AND & AM 57 THIS HAS TAKEN HIS TOLL VRS OID, BUT I Aferro To Close He Bott ON Any of My 12 Mart TOS & Wait ON. ANY offer give Smith To Look Kitte But Kemington You TH'S_ Built it and I only TRUST You To CHark & MAKE Repairs I Pit TAPE ON the Spenie Round Covering PRIMER & DUCE of FIRE & SALT DID FIRING PIN MAKE A the in TARE OVER PRIMER, I HAVE TRIED HUNDORDS of Time But only once Both Safley ou \$ Off Did it Fire But THAts 2 Times two MANY Please MARE Repairs To Rifle Weer I CAN HAVE

the Piece of MIND TO Keep Using My offer Kifles along with Laffing 141 Son's & Gernosans use three's CAuse I Know you what send BACK UNLess YOUR SURCE K.fle HAPPEN Equin, KNO IF If WANT is ANY thing I CAN LOOK FOR ON MY Office Kifles Even Model TOO MI I HAVE TWO Please Me KNOW I CAN Be Keached 1 931-308-1879 MY ANY lime address RANDY Sachrough 71,3 South High Sch Winchester, TN 37398-2117 THANK You Very Klucht NOT FIND Recipi My Som UncHased THIS FOR ME. IF U NEED tak Keg OH Kitle H 15 IN MY HAME









