

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 9427 Arms Service number: 3711747

Last Name: CARDONE First Name: ROBERT

Street: 310 W MARKET ST City: WARREN

State: OH Zip: 44485 Home Ph: 330 392 7096

Work Ph: Product Type: F F A T O I

Type Concern: S P I P D P S C Concern Code: 1007

Concern: FIRED ON SAFE RELEASE

Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS

Assigned To: KAST Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 6/20/97 Date Opened by P/S: 6/20/97 Caliber: 222

Date of Incident: Date Closed: 6/20/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 722 Serial: 339054 Date Code: LA Date Mfgd: 2/1/52

RAMAC: 722 Litigation: ☐ PreLitigation: ☐ Obsolete: ☒

Custody: Comments:

Time of Modification: 12:51:56 PM Date of Modification: 6/20/97

Form View

FLTR

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 97-11747INITIAL  
JJM

CUSTOMER ORDER NO.

PRODUCT SERVICE  
BOTTOM HALF OF MOUNTS ONLYDATE RECEIVED  
06/18/97DATE OPENED  
06/20/97DATE CODE  
LA 2-54SERIAL NUMBER  
339054

NEW SERIAL NUMBER

MODEL AND GRADE  
722 222

ACCESSORIES

SCOPE BASE

W/STUDS

W/SWIVELS

L/REAR SIGHT

FROM:

CARDONE, ROBERT J  
310 W MARKET ST  
WARREN

OH 44485

SHIP TO:

CARDONE, ROBERT J  
310 W MARKET ST  
WARRENOH  
44485

CUST NO: 169514 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Fires on bolt closing and when safe is taken off, due to altered sear engagement. Exchange trigger assy. at a special price strictly as a gesture of goodwill. Open inletting for m too trigger assy.

PARTS

COMMENTS

Trigger Assy.

Instructions to measure trigger pull as seen.

Grease found inside trigger assy.

Sear engagement only .005

See owners manual for proper care and maintenance

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

FD6925 REV. 6/96

PS 34483

June 12, 1997

Remington Arms Co.  
REPAIR DEPT.  
14 Hoefler Ave.  
Ilion, N. Y. 13357


Dear repair Dept.:

I am sending my Model 722 (serial #339054) for repairs. This 222 Cal. rifle is the only Remington gun, that has given me a problem.

The dilemma I have is the rifle discharges when the safety is placed off from the on position. I would like to have your people do the necessary repairs for me.

If there are any questions please contact me at (330)392-7096 during the business day and at (330)759-3156 after 6:00 P.M..

Thank You,



Robert J. Cardone  
2310 W. Market St.  
Warren, Oh. 44485  
(330)392-7096