

File Number:	9525	Arms Service number:	9710618
Last Name:	CONKLIN	First Name:	LAWRENCE J
Street:	342 ST MARYS DRIVE	City:	STEVENSVILLE
State:	MT	Zip:	59870
		Home Ph:	406-777-3747
Work Ph:		Product Type:	F F A T
Type Concern:	S P I PD P S	Concern Code:	1008
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	6/4/97	Date Opened by P/S:	9/3/97
		Caliber:	6.5 MAG
Date of Incident:	9/1/95	Date Closed:	9/4/97
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	6214630
		Date Code:	RS
		Date Mfgd:	1/1/69
RAMAC:	700	Litigation:	☐
		PreLitigation:	☐
		Obsolete:	☐
Custody:		Comments:	Gummy, sticky residue and altered adjustments - Replace trigger assembly at special price
Time of Modification:	12:44:25 PM	Date of Modification:	9/4/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service

ORDER

R 97-10618 ✓

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/29/97

06/04/97

BS 1-69

6214630

700

6.5MAG

BDL

ACCESSORIES

SCOPE BASE

L/SIGHTS

W/STUDS

FROM:

SHIP TO:

CONKLIN, LAWRENCE J
342 ST MARYS DRIVE
STEVENSVILLE

MT 59870

CONKLIN, LAWRENCE J
342 ST MARYS DRIVE
STEVENSVILLEMT
59870

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 167714 C.O.D.

WRITE ☐

PROM. DATE

ESTIMATED

VIA

9-397

HPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

33.00

*add no other
cost*

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

*My 1969 Upon receipt we could not duplicate the
reported concern, however examination did reveal that the trigger &
bolt stop release were working very sluggish from being covered with
a heavy sticky substance. The trigger & stop screws should
also be adjusted.*

PARTS

COMMENTS

#26345

*Replace the trigger
screw at 1/2 normal repair
cost go ahead*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11-95

Remington Arms
"700 CALL BACK"
14 HOESLER AV.
ILION NY. 13357

Gentlemen,

I Purchased This Fine Rifle
Several years ago, As A USED gun, AT
A LOCAL GUN STORE. IT HAS SERVED ME WELL
AND I HAVE TAKEN MANY HEAD OF GAME
WITH IT, USUALLY WITH ONE SHOT. I HAND
LOAD, USING 54gr, H4831, AND THE 140gr.
BOAT TAILS FROM SIERRA, OR NOSLER.
THE ACCURACY HAS BEEN OUTSTANDING, (I HAVE
EVEN WON BENCH REST "TURKEY SHOOT" MATCHES
WITH IT - SEE TARGET ENCLOSED.)

HOWEVER, THE LAST COUPLE OF YEARS
IT HAS "GONE OFF" UNINTENTIONALLY, WHEN
I CHAMBERED A ROUND, SCARING ME, AND MY
HUNTING COMPANIONS, ON TWO OCCASIONS.
I TOOK IT IN TO A GUN SMITH, AND HE
SUGGESTED I SEND IT IN TO YOU -

THESE INCIDENTS HAPPENED AFTER RIDING
MANY MILES IN A PICKUP TRUCK, GAME WOULD
BE SPOTTED, I WOULD STEP OUT, CLEAR

of the vehicle, AND close the
feeding A Round From The Magazine
(LEGAL IN THIS STATE TO CARRY ROUNDS
IN THE MAGAZINE)

I ALWAYS HAVE THE MUZZLE POINTED
UP, SO WHEN I CLOSED THE BOLT, AND
THE ROUND WENT OFF, NO DAMAGE WAS
DONE; EXCEPT FOR SOME RAZZING FROM
MY PARTNERS - THIS LAST TIME, I DROPPED
THE DEER WITH A SECOND SHOT AS IT BOUNCED
ACROSS THE FIELDS; AND THE FELLOW WHO
WAS DRIVING SAID, "NICE SHOT, BUT WE
USUALLY DON'T GIVE THEM A WARNING SHOT."

PLEASE SEE WHAT YOU CAN DO
TO RECTIFY THE PROBLEM.

THANKS

LARRY CONKLIN

RETURN TO:

LAURENCE J. CONKLIN

342 ST. MARY DRIVE

STEVENSVILLE, MT.

59870

PHONE (406) 777-3747

Remington Arms
Back
to
Cal
A.