

Customer Service Data Entry			
File Number: 9267		Arms Service number: 9706796	
Last Name: MCCELLANDS GUN SHOP		First Name:	
Street: 1533 CENTERVILLE RD		City: DALLAS	
State: TX		Zip: 75228	
Home Ph:		Work Ph:	
Product Type: F		F A T O	
Type Concern: S		PI PO P S C	
Concern Code: 1007		Concern: FIRED ON SAFE RELEASE	
Cause Code: 4015		Cause: IMPROPER MAINTENANCE	
Assigned To: SANITA		Classification: UNJ UNJ UNJ UNJ	
Settlement Detail: REPAIR AT SPEC. PRICE		Settlement Amount: \$0.00	
Date Opened Rem: 3/20/97		Date Opened by P/S: 3/20/97	
Caliber: 270		Date of Incident:	
Date Closed: 3/20/97		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
Manufacturer: REM		Model: 700	
Serial: A6359260		Date Code: 01	
Date Mfgd: 9/1/78		RAMAC: 700	
Litigation: ☐		PreLitigation: ☐	
Obsolete: ☐		Custody:	
Comments:		Time of Modification: 1:20:40 PM	
Date of Modification: 3/20/97			

Additional info:

FLTR

CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-06796

INITIAL CUSTOMER ORDER NO.

PRODUCT SERVICE

JJM

DATE RECEIVED
03/19/97DATE OPENED
03/20/97DATE CODE
DI 9-76SERIAL NUMBER
A6359260

NEW SERIAL NUMBER

MODEL AND GRADE
700 270

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO: 006612 WILL

ACCOUNT NUMBER

ACCOUNT NUMBER NIC

WRITE ☐

PROV. DATE

ESTIMATED

VIA
UFS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

33.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D1	E4	F4
WOOD			C1	D2	E5	F5
METAL			C2	D3		

MAIN FAULT

Ref'd Mfg 1976, upon receipt we could not duplicate the reported concern. However we did note that the bolt stop rubber and gun safety cam is wearing, sluggish. The action is smooth the trigger housing is covered with dust & a heavy sticky substance.

PARTS

COMMENTS

Ref'd Mfg 1976, upon receipt we could not duplicate the reported concern. However we did note that the bolt stop rubber and gun safety cam is wearing, sluggish. The action is smooth the trigger housing is covered with dust & a heavy sticky substance.

Repair complete trigger cam.
& clean the action w/ 1/2 the normal
upward cost

#26345

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 6/96

PS 34745

03/11/97

Invoice No. 46025
Date Recd. 03/11/97

TERMS OPEN

Company Name REMINGTON ARMS CO, INC
Post Office Box 14 HOFELR AV
Street Address SERVICE DEPT
City State Zip ILION,NY 13357

PS 34746