

File Number:	9625	Arms Service number:	9717537
Last Name:	MCCONOCHE	First Name:	WILLIAM
Street:	71 E 15TH AVE	City:	EUGENE
State:	OR	Zip:	97401
Home Ph:		Home Ph:	541 686 9934
Work Ph:		Product Type:	F A T O
Type Concern:	S	PL PD P S C	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	KAST	Classification:	UNJ
Settlement Details:	REPAIR SPOL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	10/14/97	Date Opened by P/S:	10/24/97
Date of Incident:		Date Closed:	10/24/97
Date to Analysis:		Date from Analysis:	
Model:	9717537	Serial:	6520055
RAMAC:	9717537	Litigation:	
Custody:		Comments:	
Manufacturer:	REM	Date Mfgd:	3/1/72
Caliber:	7MMMA	Bullet Weight:	
Obsolete:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Time of Modification:	11:17:16 AM	Date of Modification:	10/24/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

product Service

ORDER

R 97-17537

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

10/13/97

10/14/97

AW 3-72

6526065

700

7MMAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

MCCONOCHIE, WILLIAM A
71 E 15TH AVE
EUGENE.

OR 97401

MCCONOCHIE, WILLIAM A
71 E 15TH AVE
EUGENE

OR

97401

CUST NO: 174638 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

42.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

total

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

All three trigger adjusting screws have been altered
outside of the factory. Not recommended.

Exchange trig assy at a spec price strictly as a
gesture of good will.

PARTS

COMMENTS

trig. Assy New Style

Trig pull 3 LBS as rec'd

Bolt stop stuck when engaged.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7-97

PS 34748

William A. McConochie
71 E. 15th Ave.
Eugene, Or. 97401

9-24-97

Re: Rifle firing when safety switch turned from Safe to Fire.

Reminton Arms Co.
Attn: Production Service.
14 Hoefler Ave.
Ilion, N.Y. 13357

Dear Sirs:

I recently was ending my hunting day with my Reminton model 700 rifle and pushed the safety switch from safe to fire. The gun immediately fired a round, tearing open my thumb.

I have spoken with other hunters who tell me the model 700 is know for such problems but that you can fix them. I spoke with one of your personnel on the phone yesterday. He told me to send the gun to you for service.

Specifically, he said you could replace the firing mechanism with one that will allow me to empty the chamber and magazine of live rounds with the safety switch still on safe, for a fee of \$43.00. That is what I would like you to do.

If you see any other problems that need service, please proceed, unless additional expense is necessary. In that case, please call me at 541-686-9934.

Also, please send me a booklet for cleaning and lubricating my 700, as I bought it years ago from another hunter and don't have a booklet.

Thank you very much.

Yours truly,

William A. McConochie

William A. McConochie

Enclosure: 1 model 700 7mm magnum Reminton rifle.