

File Number:	9012	Arms Service number:	9701765
Last Name:	SHOOTING SPORTS	First Name:	
Street:	TRYONE UMLAUF RT 6 BOX 184	City:	LITTLE FALLS
State:	MN	Zip:	56345
Work Ph:	320 632 9204	Home Ph:	
Type Concern:	PD	Product Type:	F F A T
	PI PD P S	Concern Code:	1008
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	KAST	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT N/C	Settlement Amount:	\$0.00
Date Opened Rem:	1/21/97	Date Opened by P/S:	1/22/97
Date of Incident:	11/9/96	Caliber:	270
	Date Closed:	Bullet Weight:	
	1/22/97		
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	B6468339
		Date Code:	OD
RAM/AC:	700	Date Mfgd:	7/1/83
		Litigation:	
		PreLitigation:	
		Obsolete:	
Custody:		Comments:	SEAR & TRIGGER GUMMED UP - SHOT HOLE THRU TRUCK DOOR EST. DAMA \$867.80
Time of Modification:	2:54:41 PM	Date of Modification:	1/22/97

RECEIVING AND ESTIMATING REPORT		COMMENTS	ORDER R 97-01765
---------------------------------	--	----------	---------------------

INITIAL JJM	CUSTOMER ORDER NO.		PRODUCT SERVICE	
DATE RECEIVED 01/14/97	DATE OPENED 01/21/97	DATE CODE 00 7-83	SERIAL NUMBER B6468339	NEW SERIAL NUMBER
ACCESSORIES		W/STUDS	SCOPE BASE	MODEL AND GRADE 700 270 BDL/LH
		L/SIGHTS		

FROM:	SHIP TO:
SHOOTING SPORTS TRYONE UMLAUF RT 6 BOX 184 LITTLE FALLS MN 56345	SHOOTING SPORTS TRYONE UMLAUF RT 6 BOX 184 LITTLE FALLS MN 56345

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION	REPAIR CHARGE
<input type="checkbox"/> NEW	EXCISE
<input type="checkbox"/> LIGHTLY WORN	TAX
<input type="checkbox"/> WORN	INSURANCE
<input type="checkbox"/> VERY WORN	UPS
<input type="checkbox"/> UNREPAIRABLE	PARCEL POST
<input type="checkbox"/> MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	B1					
TRIGGER GROUP				E1	F1	
BOLT ASSY.	B3			E2	F2	
BARREL ASSY.						
REC. ASSY.	B5		C2		F4	
WOOD						
METAL						
<p>MAIN FAULT: <i>Sear is sticking in trigger housing as rec'd. - Trigger is sluggish. Reason is that both sear and trigger are gummed up with old solidified oil. Exchange trigger Assy. at a special price strictly as a gesture of good will. N/C</i></p>						

PARTS	COMMENTS				
<i>Trigger Assy</i>	<i>Trigger pull 3 1/2 LBS as rec'd.</i>				
	<i>Sear engagement OK</i>				
	<i>See owners manual for proper care and maintenance.</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

TO WHOM IT MAY CONCERN:

PERFORMANCE OF A 700 BDL LH RIFLE IN 270 CAL.

ON SATURDAY, NOVEMBER 9, 1996, I DROVE OUT TO THE STAND ON MY FARM. I TOOK MY CASED RIFLE OUT OF MY TRUCK & REMOVED IT FROM THE CASE. I LOADED 4 CARTRIDGES INTO THE MAGAZINE & CLOSED THE BOLT. THE RIFLE WENT OFF PASSING THROUGH THE PASSENGER SIDE DOOR. I IMMEDIATELY DROPPED THE HINGE PLATE & REMOVED THE REMAINING 3 CARTRIDGES. I THEN CYCLED THE BOLT & THE FIRING PIN WENT FORWARD AGAIN WITHOUT MY TOUCHING THE TRIGGER. I CONSIDER MYSELF LUCKY AS THE ONLY DAMAGE WAS TO THE TRUCK DOOR. I CYCLED THE RIFLE SEVERAL MORE TIMES BUT AFTER THAT IT FUNCTIONED PROPERLY. THE AIR TEMPERATURE WAS ABOUT 20 DEGREES F.

THE FOLLOWING DAY I WENT UP ON STAND AGAIN. WHEN I LOADED & CYCLED RIFLE IT WORKED PROPERLY. AFTER ABOUT AN HOUR ON THE STAND I HAD A SHOT AT SEVERAL DEER GOING BY. WHEN I EJECTED THE EMPTY AND CLOSED THE BOLT SLOWLY, I TOOK ANOTHER SHOT. NOTHING HAPPENED. THE FIRING PIN HAD GONE FORWARD WHEN I CLOSED THE BOLT BUT DID NOT FIRE THE CARTRIDGE.

I LEFT THE STAND, WENT HOME & BROUGHT BACK ANOTHER RIFLE.

ABOUT A WEEK AGO I HAD THE RIFLE IN THE CASE IN THE TRUCK. I TOOK THE RIFLE TO THE DEALER THAT I BOUGHT IT FROM.

WHEN I REMOVED THE RIFLE FROM THE CASE, I CYCLED IT TWICE ON AN EMPTY CHAMBER. THE FIRING PIN WENT FORWARD BOTH TIMES. AFTER THE FIRST TWO TIMES IT FUNCTIONED PROPERLY.

1-3-97

SINCERELY YOURS,



EARL L. NIEMAN  
RTE 5, BOX 201  
LITTLE FALLS, MN 56345  
1-320-745-2616

ENCLOSURES: REPAIR ESTIMATE FOR TRUCK DOOR



# SHOOTING SPORTS

6 • Box 184  
Little Falls, MN 56345  
632-9204  
Do



Attn: Repair Dept.

Enclosed is Remington 700 BDL LH

Ser# B6468339. Along with  
Customer's letter. Please look  
over the rifle and call  
me after you have decided  
what to do on this matter.

*Myron Unlauf*

320-632-9204

HE STAND ON MY FARM.  
IT FROM THE CASE. I  
THE BOLT. THE RIFLE  
R. I IMMEDIATELY DROPPED  
EDGES. I THEN CYCLED  
THOUT MY TOUCHING THE  
PAGE WAS TO THE TRUCK  
T AFTER THAT IT FUNCTIONED  
REES F.

N I LOADED & CYCLED  
IN THE STAND I HAD A SHOT  
PTY AND CLOSED THE BOLT  
THE FIRING PIN HAD  
FIRE THE CARTRIDGE.

HER RIFLE.

THE TRUCK. I TOOK THE

D IT TWICE ON AN EMPTY  
I. AFTER THE FIRST TWO

SINCERELY YOURS,

*Carl L. Nieman*  
CARL L. NIEMAN  
TE 5, BOX 201  
ITTLE FALLS, MN 56345  
-320-745-2616

ENCLOSURES: REPAIR ESTIMATE FOR TRUCK DOOR