

Customer Service Data Entry	
File Number: 9325	Arms Service number: 9708392
Last Name: SONS SPORT SHOP	First Name:
Street: 2840 H	City: MOUNDS VIEW
State: MN	Zip: 55112
Home Ph:	
Work Ph:	Product Type: F A T O
Type Concern: P P D P S C	Concern Code: 1008
Concern: FIRE	
Cause Code:	Cause: IMPROPER MAINTENANCE
Assigned To: JST	Classification: UNC UNJ UNC UND J
Settlement Det: REPAIR SPCL PRICE	Settlement Amount: \$0.00
Date Opened: 4/21/97	Date Opened by P/S: 4/21/97
Date of Incident:	Caliber: 30-06
Date to Analysis:	Date Closed: 4/22/97
	Bullet Weight:
Date from Analysis:	Manufacturer: REM
Model: 700	Serial: B6405565
	Date Code: WD
	Date Mfgd: 8/1/88
HAMAC: 700	Litigation: <input type="checkbox"/>
	PreLitigation: <input type="checkbox"/>
	Obsolete: <input type="checkbox"/>
Custody:	Comments:
Time of Modification: 1:43:35 PM	Date of Modification: 4/22/97

Form View

FLTR CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-08392

INITIAL CUSTOMER ORDER NO.

PRODUCT SERVICE

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/18/97

04/21/97

WD 8-83

B6485565

700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SIMONS SPORT SHOP
2840 HWY 10
MOUNDS VIEW

MN 55112

SHIP TO:

SIMONS SPORT SHOP
2840 HWY 10
MOUNDS VIEWMN
55112

CUST NO: 002862 ILIONL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A

B

TRIGGER GROUP

• FIRED when closing bolt

BOLT ASSY.

B3

BARREL ASSY.

• Hang Fire

REC. ASSY.

B5

WOOD

• MISFIRES

METAL

C2

MAIN FAULT

Unable to duplicate any of the customers concerns as recd. Gun was recently oiled. Seal and Trigger Housing were gummed up with old solidified oil. Exchange Trigger Assy. at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Trigger Assy.

Trigger pull 3 1/2 LBS as recd.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

FD6925 REV. 11.96

SIMON'S SPORT SHOP

2840 HIGHWAY 10
 MOUNDS VIEW, MN 55112
 784-2888 • FFL#41-5036

DEPARTMENT OR REQ. NO. 441789

PURCHASE ORDER

SHIP TO:

Remington Arms Co.
 Arms Service Division
 14 Hoefler Ave
 Ilion, NY 13357

DATE OF ORDER 4-10-97	DATE REQUIRED	SHIP VIA	FOB
--------------------------	---------------	----------	-----

QUANTITY	QUOTATION NUMBER	FOR RESALE <input type="checkbox"/>	FOR USE <input type="checkbox"/>
----------	------------------	-------------------------------------	----------------------------------

QUANTITY		PLEASE SUPPLY ITEMS LISTED BELOW	UNIT	PRICE	
ORDERED	RECEIVED				
		Rem 700 BDL cal 30-06 Ser No. 6485565			
		Customer complaint: Rifle fired when he closed			
		the bolt - hang-fired on another occasion and			
		has had several misfires where primer is barely			
		indented. He claims that he cleaned the Bolt			
		thoroughly with no apparent results. All ammunition			
		used is Remington 150 gr corlokt			

IMPORTANT OUR ORDER NUMBER MUST APPEAR ON INVOICES PACKAGES & CORRESPONDENCE
 ACKNOWLEDGE IF UNABLE TO DELIVER BY DATE REQUIRED

BY

ST Simon