

File Number: 11718		Arms Service number: 9915195	
Last Name: BORSKI		First Name: DON	
Street: 9619 DUNDALK ST		City: SPRING	
State: TX	Zip: 77379	Home Ph:	
Work Ph:	Product Type: F	F A T	
Type Concern: S	PI PD P S	Concern Code: 1020	
Concern: FIRED ON BOLT OPENING			
Cause Code: 4015	Cause: IMPROPER MAINTENANCE		
Assigned To: SANITA	Classification: UNJ	UNJ UNC UND	
Settlement Detail: REPAIR AT SPEC PRICE	Settlement Amount: \$0.00		
Date Opened Rem: 8/6/99	Date Opened by P/S: 8/6/99	Caliber: 270	
Date of Incident:	Date Closed: 8/10/99	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: B6308993	Date Code: KB	Date Mfgd: 5/1/81
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments:		
Time of Modification: 8:25:49 AM	Date of Modification: 8/10/99		

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 99-15195INITIAL  
PS

CUSTOMER ORDER NO.

DATE RECEIVED

08/04/99

DATE OPENED

08/06/99

DATE CODE

KB 5/81

SERIAL NUMBER

B6308993

NEW SERIAL NUMBER

MODEL AND GRADE

700 270

ADL

ACCESSORIES

W/STUDS

SCOPE MNTS

FROM:

BORSKI, DON  
9619 DUNDALK ST.  
SPRING

TX 77379

SHIP TO:

BORSKI, DON  
9619 DUNDALK ST.  
SPRINGTX  
77379

CUST NO: 212929 C.O.D L

ACCOUNT NUMBER

2293001

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

35.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

43.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D1	E4	F4
WOOD				D2	E5	F5
METAL				D3		
MAIN FAULT						

W/ 1981 Upon receipt we could not duplicate the reported concern, but did find the bolt stop, release & trigger working sluggish from being covered with dirt, rust, & a heavy sticky substance. Action also covered with dirt. Rifle poorly maintained.

PARTS	COMMENTS
#21345	Replace the complete trigger group & clean the action at 1/2 normal cost
REPAIRMAN	PROOF
CLEAN	TEST
TARGET	PATTERN
GALLERY TESTER	DATE
DATE	DATE
DATE	DATE
DATE	DATE

OFFICE COPY

RD6925 REV. 7/97

**To:** Dennis Sanita @ REMINGTON ARMS PRODUCT SERVICE  
DEPARTMENT

**Cc:** 14 HOEFLER AVENUE / ILION; N.Y. 13357 / ATTN: DENNIS  
SANITA

**Subject:** RETURN OF MODEL 700 ADL RIFLE, S/N B6308993

Dear Mr. Sanita:

Per  
our telephone conversation of 7/20/99, I am returning a Model 700  
ADL Bolt-Action rifle for repair. As we discussed, the rifle has accidentally  
discharged a round on two occasions while I was trying to unload the  
magazine. This style rifle does not have a bottom clip to unload & each round  
must be injected into the chamber in order to unload. Each time the round  
fired as the round was chambered and luckily no one was injured, only a hole  
in my vehicle. You mentioned there was not a recall issued on this model  
rifle, but apparently something is inherently wrong with the concept of not  
being able to unload a weapon without first chambering a round. I would  
appreciate Remington Arms taking a look at this problem and repairing or  
otherwise fixing the problem so that I can feel comfortable using this rifle  
once again. You can contact me during the day @ 1-800-892-9965, or 281-  
463-6660, ext 108. My home number is 281-376-4133. My return address is:

Don H Borski

Spring, TX 77379

appreciate a quick response to this problem.

Borski

9619 Dundalk St

I would

Thanks, Don