

File Number:	12606		Arms Service number:	00000449	
Last Name:	CURTIS		First Name:	PAUL D	
Street:	170 SE 3RD STREET		City:	BEND	
State:	OR	Zip:	97702	Home Ph:	541-389-9559
Work Ph:	541-382-6569	Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPLACE TPA N/C		Settlement Amount:	\$40.00	
Date Opened Rem:	12/14/99	Date Opened by P/S:	12/20/99	Caliber:	30-06
Date of Incident:		Date Closed:	12/21/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	E6541668	Date Code:	
RAMAC:	700	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	As received firing pin follows-down - Sear engagement appears to have been reset after it left the factory - Replace TPA n/c as gesture of goodwill.		
Time of Modification:	9:35:34 AM	Date of Modification:	12/21/99		

Serial Number: E6541668

Model ID: 700



RE00000449

As received follows down

Scar engagement

Appears to have been reset
after it left factory

- Replace TPA as gesture of
goodwill.

FCS

12/17/99

REMINGTON REPAIR INSTRUCTIONS

Name: Paul D Curtis
Mailing Address: 170 SE 3rd St
Bend OR 97702

Model: 700 ADL
Serial #: E6541668 / or 47700274

Telephone: Day 541 382-6569
Evening 541 382-9559

Date of Purchase: 20 Oct 99
(If available, please attach a copy of the proof of purchase.)

Please describe the problem you are having with your firearm: Does Not Cock when Bolt is Placed in the Home Position when the Safety is off. When safety is on Bolt will cock, but will fire when safety is moved to fire

Optional Information:

Ammo Type: 30-06 Remington Brand Remington or Handload Specifications: _____
Bullet Weight: 180 gr Shot Size: _____

If your firearm has previously been repaired/evaluated by Remington or a Remington Authorized Repair Center, please provide copies of your repair paperwork.

Your firearm will be evaluated using the following criteria to determine if the repair will be charged to Remington: Date of Purchase Type of Repair Condition/Owner Maintenance

Payment

Chargeable repairs under \$75 will be completed and returned C.O.D.. To avoid C.O.D processing, you may provide credit card authorization now. An estimate will be mailed for repairs over \$75. If you wish, you can also expedite repairs over \$75 by setting a pre-authorized amount that can be billed to your credit card.

You may repair my firearm and bill my credit card for charges up to \$ _____.

Credit Card Number: 5491-1400-1119-2449 Expiration Date: 01/01
(American Express, Discover, MasterCard, or Visa)

Signature: Paul D Curtis

Please call
if not covered
under warranty

Reminders:

Record your serial number—it will help reference your repair.
Properly package your unloaded firearm. Do not ship in a hard case. If you would like to order a box, please call our Parts Department: 800-243-9700, 9 a.m.-5 p.m., EST.
Do not send live/loaded ammunition with your firearm.
Remove all accessories.