

File Number:	12090		Arms Service number:	9923079	
Last Name:	MARTENEZ POLICE DEPT		First Name:		
Street:	525 HENRIETTA ST		City:	MARTINEZ	
State:	CA	Zip:	94553	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD F S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SANITA	Classification:	UNC	UNJ UNC UND	
Settlement Detail:	REPLACE TRIGGER ASSEMBLY AT N/C			Settlement Amount:	\$0.00
Date Opened Rem:	11/22/99	Date Opened by P/S:	11/23/99	Caliber:	308
Date of Incident:		Date Closed:	11/23/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	C6871268	Date Code:	DL
RAMAC:	700	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>		
Comments:					
Time of Modification:	2:45:12 PM		Date of Modification:	11/23/99	

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 99-23079INITIAL  
PS

CUSTOMER ORDER NO.

ATTN: DET. MIKE THOMPSON

DATE RECEIVED  
11/19/99DATE OPENED  
11/22/99DATE CODE  
DL 9/91SERIAL NUMBER  
C6671256

NEW SERIAL NUMBER

MODEL AND GRADE  
700 308

POLICE/SYN

ACCESSORIES

W/STUDS

HARD CASE

SCOPE BASE

FROM:

SHIP TO:

MARTINEZ POLICE DEPT  
525 HENRIETTA ST  
MARTINEZ

CA 94553

MARTINEZ POLICE DEPT  
525 HENRIETTA ST  
MARTINEZ

CA

94553

CUST NO: 067345 C.J.O.D.

ATTN: Mike Thompson

ACCOUNT NUMBER

ACCOUNT NUMBER INC

WRITE ☐

FROM DATE

ESTIMATE

DATE

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

added to order

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

C2

Unintentional discharge  
when changing the slide assembly

MAIN FAULT

Upon receipt we could not duplicate the above concern, but  
did not throw away the action, trigger assembly, & in the morning  
duty. Left with a good feeling.

COMMENTS

Replace the complete trigger  
assembly at the suggestion  
of Goodman - who clean  
action

REPAIR PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

City of Martinez

POLICE DEPARTMENT

5 Henrietta Street, Martinez, CA 94553-2394

10, 1999

on Arms Inc.

er

Y 13357

on: Customer Service

omer Service,

Sniper recently experienced an unintentional discharge with the enclosed weapon, Remington Model 700, serial C6671256, when he was pushing the bolt into battery on a live round. Fortunately the weapon was pointed at the ground and the weapon discharged harmlessly into the ground. The officer said he was using his right hand to push the bolt home and was no where near the trigger at the time of discharge. We are requesting a complete examination and repair/adjustment as necessary. Please notify me of the estimated cost prior to performing the needed repairs.

I have talked to another agency in the area and they claim to have suffered a similar event. We are wondering if the weapon should be sent in on a regular basis, perhaps after so many rounds, for a regular adjustment/inspection to prevent this type of accident. Please advise.

Please repair as soon as possible and return to:

Martinez Police Department  
525 Henrietta St.  
Martinez, CA 94553.  
Attention: Detective Mike Thompson.

If you have any questions, please contact Detective Thompson at (925)372-3453.

Thank you,

Chief David Cutaia

by:

*M. Thompson*  
Detective Mike Thompson

Note: This is one of only two sniper rifles our department owns, Please expedite repairs.  
Thank you.