

File Number:	11470	Arms Service number:	9909190
Last Name:	MORRIS	First Name:	KENNETH
Street:	1194 HUDSON CT	City:	SIMI VALLEY
State:	CA	Zip:	93065
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T
Concern:	F I R E D O N B O L T C L O S I N G		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANTA	Classification:	UNI
Settlement Detail:	REPAIR AT SPECIAL PRICE		
Date Opened Rem:	04/06/1999	Date Opened by P/S:	04/06/1999
Date of Incident:		Date Closed:	04/12/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	6507624
RAMAC:	700	Litigation:	
Custody:		Comments:	
Time of Modification:	1:12:42 PM	Date of Modification:	04/12/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-09190

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/06/99

04/08/99

XU 12-71

6507624

700 22-250

BDL/VAR

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

MORRIS, KENNETH
1194 HUDSON CT
SIMI VALLEY

CA 93065

MORRIS, KENNETH
1194 HUDSON CT
SIMI VALLEY

CA
93065

CUST NO: 207239 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D1

METAL

C2

D3

MAIN FAULT

PARTS

COMMENTS

#26345

1008
4015
4006

Replace the complete
trigger group at 1/2 the normal
cost - go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD5925 REV. 7/97

KENNETH W. MORRIS

1194 Hudson Court
Simi Valley, CA 93065

Phone: 805-581-1532
E-Mail: kenwmorris@AOL.com

March 25, 1999

Remington Arm Company
Attn: Dennis Sanita
14 Hoefler Ave
Ilion, NY 13357

Dear Dennis:

Enclosed is my Remington Model 700 BDL serial number 6507624.

This is the rifle I spoke of during our phone call the week of march 16th. The rifle has been in my possession since new in 1972.

I experience a discharge while closing the bolt about 1974 and assumed my finger was on the trigger. (I'm a lefty shooter) The rifle repeated the discharge upon bolt closing again in about 6 months (EST 200 rounds), and this time I knew the rifle was the problem. I had the local smith check it out. He adjusted the trigger pull but found no problem with the rifle. He function tested it and told me it was fine.

I used the rifle for about a year without another problem. (another 200-300 rounds). The rifle was inactive for several year while I was stationed overseas etc. and was used again briefly in 1987. The discharge problem reoccurred and I stopped using the rifle. (lack of time due to work etc..)

I am now going to restart shooting this rifle. While cleaning the rifle in preparation for the range (it was oiled etc. for storage) I once again experience dry fire on closing the bolt. (finger not anywhere near the trigger).

Please evaluate this problem and do what is necessary to repair the rifle. I am very concerned that the intermittent nature of this problem will allow the rifle to "pass" routine functional test. Please consider this when you decide what repairs are needed.

I have packaged (double boxed) the rifle in the boxes I order from your parts department and am shipping it to you via UPS. Please advise me concerning the repair action, charges and repair time as soon as possible.

Sincerely,



Kenneth W. Morris