

File Number:	12556		Arms Service number:	9923771	
Last Name:	ROBINSON		First Name:	MITCH	
Street:	11381 LA SALLE STREET		City:	YALE	
State:	MI	Zip:	48097	Home Ph:	810-387-2796
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - COULD NOT DUPLICATE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPLACE TPA N/C			Settlement Amount:	\$40.00
Date Opened Rem:	12/3/99	Date Opened by P/S:	12/9/99	Caliber:	30-06
Date of Incident:		Date Closed:	12/9/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	T6246066	Date Code:	ES
Date Mfgd:	10/1/98	RAMAC:	700	Litigation:	<input type="checkbox"/>
PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	Could not duplicate customers FSR concern. Replace TPA at n/c as gesture of goodwill.		
Time of Modification:	2:35:45 PM		Date of Modification:	12/9/99	

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 99-23771INITIAL  
TEF

CUSTOMER ORDER NO.

DATE RECEIVED

12/02/99

DATE OPENED

12/03/99

DATE CODE

ES 10-98

SERIAL NUMBER

T6246066

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

EDL/SS/DM

ACCESSORIES

W/STUDS

ENHANCED

FROM:

ROBINSON MITCH  
11381 LA SALLE STREET  
YALE

MI 48097

SHIP TO:

ROBINSON MITCH  
11381 LA SALLE STREET  
YALE MI 48097

CUST NO: 215427 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

FROM DATE

ESTIMATED

12/8

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

PRODUCT SERVICE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

N/C

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Could not duplicate customer concern

PARTS

COMMENTS

Replace TPA at n/c to restore  
customer's confidence.

FCS 12/9/99

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD5925 REV. 7 97

11381 LaSalle Street  
Yale, MI 48097  
November 22, 1999

Hello:

I purchased the enclosed rifle on August 25, 1999. I purchased the rifle at Bass Pro Shops Outdoor World located in Auburn Hills, Michigan.

On November 9, 1999, I took the rifle to a local gun range to sight it in. I fired the gun 15 times. Since I was at a range, I never placed any shells in the magazine. Instead, I loaded one shell at a time directly into the chamber. I am very familiar with your Model 700 because I own 2 other 700s: one chambered in a .270 and one in a 7 mm magnum.

On Friday, November 19, I was sitting in my blind deer hunting. A deer appeared, and I placed the forearm of the rifle on my blind's shooting rail. I placed my thumb behind the safety and my index finger in front of the safety. I then moved the safety to the fire position. When the safety tang hit the fire position, the gun discharged. There was absolutely nothing in or around the trigger. This caught me completely by surprise and even scared me a little as nothing like this has ever happened to me before. I am not a new hunter. I am 56 years old and have been hunting for over 40 years, killing more than 40 deer. I have also hunted in Alaska, Alabama, and Colorado. Fortunately, no one was hurt as I always do my best to practice safe gun handling.

In my mind, I don't think that I can ever trust this particular rifle again. If you do or do not find something wrong with it and send the same rifle back, I'm going to trade it in on a Weatherby or a Browning.

Thank you for your time.

Luck,

*Mitch Robinson*

Mitch Robinson

TEL # 810-387-2796

11381 LaSalle Street  
Yale, MI 48097  
November 22, 1999

Hello:

I purchased the enclosed rifle on August 25, 1999. I purchased the rifle at Bass Pro Shops Outdoor World located in Auburn Hills, Michigan.

On November 9, 1999, I took the rifle to a local gun range to sight it in. I fired the gun 15 times. Since I was at a range, I never placed any shells in the magazine. Instead, I loaded one shell at a time directly into the chamber. I am very familiar with your Model 700 because I own 2 other 700s: one chambered in a .270 and one in a 7 mm magnum.

On Friday, November 19, I was sitting in my blind deer hunting. A deer appeared, and I placed the forearm of the rifle on my blind's shooting rail. I placed my thumb behind the safety and my index finger in front of the safety. I then moved the safety to the fire position. When the safety tang hit the fire position, the gun discharged. There was absolutely nothing in or around the trigger. This caught me completely by surprise and even scared me a little as nothing like this has ever happened to me before. I am not a new hunter. I am 56 years old and have been hunting for over 40 years, killing more than 40 deer. I have also hunted in Alaska, Alabama, and Colorado. Fortunately, no one was hurt as I always do my best to practice safe gun handling.

In my mind, I don't think that I can ever trust this particular rifle again. If you do or do not find something wrong with it and send the same rifle back, I'm going to trade it in on a Weatherby or a Browning.

Thank you for your time.

Luck,

*Mitch Robinson*

Mitch Robinson

TEL # 810-387-2796