

File Number:	11394	Arms Service number:	9906905
Last Name:	SITTER	First Name:	JOE
Street:	33201 E. DRINKWATER RD	City:	LONE JACK
State:	MO	Zip:	64070
Home Ph:			
Work Ph:		Product Type:	F F A T
Type Concern:	S PI PD P S	Concern Code:	1008
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	03/12/1999	Date Opened by P/S:	03/12/1999
Caliber:	25/06		
Date of Incident:		Date Closed:	03/15/1999
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	6337292
Date Code:	DK	Date Mfgd:	09/01/1963
RAMAC:	700	Litigation:	<input type="checkbox"/>
PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Custody:		Comments:	
Time of Modification:	1:03:24 PM	Date of Modification:	03/16/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-04905INITIAL
PS

CUSTOMER ORDER NO.

W/PACHMAYR RECOIL PAD
W/SCOPE RINGS L/REAR SIGHT

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/04/99

03/12/99

DK 9-63

6337292

700 25-06

RDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

SITTER, JOE M
33201 E DRINKWATER RD
LONE JACK

MO 64070

SITTER, JOE M
33201 E DRINKWATER RD
LONE JACK MO
64070

CUST NO: 207033 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

30.00

8.00

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

D2

E4

F4

E5

F5

MAIN FAULT

PARTS

COMMENTS

#26345

Replace the complete trigger
assembly & clean the action at
1/2 the normal cost

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Dear Sir

Please find enclosed a Remington Model 700- 25-06. This rifle has on two separate occasions fired as the bolt was being grasped while preparing to unload a live round. On both occasions the safety was disengaged and the bolt handle was touched prior to lifting the bolt handle when the rifle somehow fired.

The first time this occurred we were leaving the field and as we were unloading our weapons this one went off. We immediately took the rifle to a gunsmith and he checked it over and found nothing wrong. He suggested that perhaps a weed seed had lodged in the mechanism and caused the problem.

The second time though was at the range and I had cleaned the rifle to the best of my ability including using rather light air pressure on the trigger mechanism to be sure it was free of particles. I had fired approx. 50 rounds when I tried to again eject a live round and it fired again on its own.

Please repair this before someone is hurt. Thank you in advance for your consideration. If I can help in any way please call me at (816) 697-2747 or E-mail At Jshoer@aol.com.

Sincerely,

John M. Sitter
33201 E. Drinkwater Rd.
Lone Jack, Mo. 64070