COPIES TO:	C.K. DAVIS D.F. CARPENTER W.O. REISINGER B.E. STRADER F.J. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY BRIDGEPORT	H.K. FAUL W.H. DAVI H.A. BROV R.H. GRAC H.J. HACK D.S. FOOT D.E. MILL S.W. ROSE R.A. WILL A.J. EROW R.E. WRIG	IS IN IMAN (5) E ER IAMSON IN
TOTAL JUSTIFIED COMPLAINTS			
MARCH 1948	•		218
MARCH 1947			123
TO DATE 1948	٠	•	838
TO DATE 1947			398
FOR 12 MONTHS ENDING MARCH 3			2038 1126
LAST 12 MONTHS RUNNING AVERAG	•	· 44	169
LAST 12 MONTHS RUNNING AVERAG			94
LAST 12 MONTHS RUNNING AVERAG	E (6 MONTHS AGO		119
COMPLAINTS ON GUNS PRODUCED WITHIN	ONE YEAR	•	
CURRENT MONTH MARCH 1948		· ".	171
OCTOBER 1947	¥		128
MARCH 1947	•	- .	92
MARCH 1946			0
FOR 12 MONTHS ENDING MARCH 31, 19	18		1621
LAST 12 MONTHS RUNNING AVERAGE ON PRODUCED WITHIN ONE YEAR.	GUNS	•	135

SHEET NO 1

COMPLAINTS ON FIREARMS FOR MONTH ENDED MARCH 31, 1948

		PRODUCED WITHIN ONE YEAR	TOTAL
# O O X O	EL 81 JACKET HEAD LOOSE FAILS TO EJECT STEMS CHAMBER NOT ACCURATE FORE-END SCREW TOO SHORT JAMS (EXTRACTOR LOOSE) SHARP EDGE ON TANG SCREW IS ABOVE SURFACE	1_	24
SPOR	RTSMAN - 12 GA.		-11
000	SHELLS STEM CHAMBER FAILS TO FEED (CARRIER DOG OUT OF ADJUSTMENT TRIGGER BINDS STOCK BROKEN) 1	1 1 1
0	HAMMER OUT OF ADJUSTMENT EXTRACTOR BROKEN	1	1
X X	BARREL FITTED WITH 20 GA. TAKE DOWN SCREW CARRIER LATCH FILED TOO MUCH	1 -6 ; .	- 1
SPOR	RTSMAN - 16 GA.	•	
X	CARRIER LATCH OUT OF SHAPE CARTRIDGE STOP OUT OF ADJUSTMENT EXTRACTOR BROKEN EXTRACTOR FILED TOO MUCH	2 1 1	. 2 1 1
Χ -	TEAR IN BARREL	-5-	-1-
SPOR	STOCK CRACKED		1
MODE	SHELLS STEM CHAMBER STOCK SPLIT DEFECTIVE STOCK (POORLY FITTED) RECEIVER DAMAGED		2 1 1 -1
	MAIN SPRING BROKEN BARREL BINDS IN REAR OF RECEIVER		1 2
MODE	SHELLS STEM CHAMBER		2

SHEET NO. 2

	•	••	
	·	PRODUCED WITHIN	
× no	EL 121	ONE YEAR	TOTAL
·X	FIRING PIN STRIKES INSIDE RIM		
ô	STEM CHAMBER	•	1
٠ŏ	RETAINER LOOSE	2	2
Ŏ	BARREL LOOSE ON RECEIVER	1	1 .
	FAILS TO EJECT	í	2
0 0 X	FAILS TO EXTRACT	•	ī
	NOT ACCURATE	2	ż
0	FAILS TO FEED	1	1
v	CARRIER OUT OF ADJUSTMENT		1
X	FIRING PIN HOLE IN BLOCK OUT OF POSITION	_	1
ô	DEFECTIVE BARREL STEMS RETAINER	2	2
U	SIEMS NEIMINEN		
		• •	10
MODE	L 141		
1	FORE-END SPLIT	1	1
0	FAILS TO EJECT	i	i
0	SEAR AND SEAR LOCK OUT OF ADJUSTMENT	•	j.
Ð	SEAR AND TRIGGER OUT OF ADJUSTMENT	·	1
0	SHELLS STEM CHAMBER	2	2
	FAILS TO FEED	. 1	1
0	FAILS TO EXTRACT		S
0	CARTRIDGE STOP BROKEN FEEDING PLUG GOES BY CARTRIDGE STOP	1	. 3
·X	TRIGGER AND RECEIVER VERY LOOSE	•	!
â	MAGAZINE LOOSE (THREADS STRIPPED)	•	
~	STOCK SPLIT	•	ż
X	FRONT SIGHT NOT ALIGNED PROPERLY	1	ī
X	ASSEMBLES HARD	1	1
	RECEIVER CRACKED		1
X	EXTRACTOR FILED TOO MUCH		_1_
		11	21
	L 241	•	•
		•	•
0	FAILS TO DISCONNECT POOR NOTCH ON FIRING PIN	2	ş
X.	BARREL LOCK DOES NOT QUALIFY		1
· ·	EXTRACTOR BROKEN	•	i
0	FAILS TO EJECT	3	. વં
X	SIGHTS OUT OF LINE	2	2 2
X	NOT ACCURATE (MUZZLE UPSET)		2
0	CARTRIDGE STOP PLUNGER TOO SHORT OR TOO LONG	1	1.
••	DEFECTIVE STOCK	1	<u> 1</u>
X	JAMS (POOR CLAW ON EXTRACTOR)	Ş	5
0	STEMS CHAMBER	† 1	1
X O	BARREL DAMAGED AT FORE-END SCREW HOLE STUD ACTION FAILS TO CLOSE PROPERLY	j	₹ 1
Ö	DISCONNECTOR DAMAGED	i	1 .
×	YOKE GROUND TOO MUCH	i	1
X	FRONT SIGHT SLOT IN BARREL IS OFF	i	1
	्राच्यार क्राच्यार क्राच्यार क्राच्या ११४ क्या १९८ व्या १७० व्या १	<u> 21 </u>	26
		~ •	

SHEET NO. 3

• •	000011650 111511111	•
•	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 31 - 12 GA. X RIB ON BARREL POOR SHAPE		
DEFECTIVE BARREL	1	1
X BARREL DENTED AND WRINKLED	Ż	į
O DROP SHELLS DEFECTIVE STOCK - GRAIN CHECK	. 1	1
•		
MODEL 31 - 16 GA.		
STOCK CHECKED	1	1
RECEIVER CRACKED FAILS TO FEED	1	. 1
STOCK BROKEN	1.	i.
RIGHT CARTRIDGE STOP NOT ADJUSTED PROPERLY	-1	
	. • • • • • • • • • • • • • • • • • • •	. 2
MODEL 31 - 20 GA. O CARTRIDGE STOP OUT OF ADJUSTMENT	•	1
DEFECTIVE STOCK (CHECKED)	ż	3
	3	-1-
MODEL 37		
DEFECTIVE SOLT	1	1
MODEL 510		
X BARREL OUT OF LINE IN RECEIVER O FAILS TO EJECT		1
BROKEN EJECTOR	į	1
X FACE OF BOLT SHALLOW X BOLT CLOSES HARD	1	} ¹
X BOLI GEOCG IMIN	-5-	- - - - -
MODEL 511	•	·
N FATES TO EJECT	1	2
O FIRING PIN FOLLOWS DOWN O SAFE OUT OF ADJUSTMENT	•	1
O SAFE OUT OF ADJUSTMENT # BOLT AND SEAR DAMAGED	1	1
	. 2	5
MODEL 512	ė.	
CARTRIDGE RETAINER OUT OF ADJUSTMENT	2	3
O EJECTOR TOO LOW O FAILS TO EJECT	1	j
# BOLT PULLS OUT	14	14
BOLT HANDLE LOOSE X DEFECTIVE BARREL (RIFLING TORN)	1	2
DAMAGED INSERT	i	ī
CARTRIDGE RETAINER AND SPRING MISSING	1	1
TOP OF INSERT BENT	-22	26
	. -	

SHEET NO. 4

-		PRODUCED WITHIN ONE YEAR	TOTAL
O X X X	STOCK CHECKED FAILS TO ELECT KEYHOLES BOLT PULLS OUT BOLT HANDLE LOOSE	32 1 1 36	1 32 31 1 37
MODE	L 521	_	
O X X	STOCK CHECKED SAFETY SCREW BROKEN DROP SHELLS ELEVATION SLIDE COMPLETE MISSING BROKEN MAGAZINE LOCK BOLT BINDS MOVING FORWARD	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 6
MODE	L 550-1 CARTRIDGE STOP BROKEN	2	2
9	FAILS TO COCK	Ī.	Ī
X O O	INSERT ROUGH (JAMS) FAILS TO EJECT	, \$.	Ç
0	FAILS TO CONNECT FAILS TO EXTRACT	1 2	1
0	NO CHAMFER ON FRONT END OF RECOIL CHAMBER	į	. 1
X O	FAULTY TRIGGER PULL LOOSE INSERT		1
X	CONNECTOR PIN LOOSE TOOL MARKS AROUND RIFLING	1	1.
x	TAKE DOWN SCREW BUSHING LOOSE	i	<u>j</u>
X	TOOL MARKS AROUND RIFLING TAKE DOWN SCREW BUSHING LOOSE	1 1 2h	7 1 2h

CORRECTED IN RECENT PRODUCTION
OVERSIGHT IN INSPECTION
CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY
TEST RESULTING IN MALFUNCTION THROUGH USAGE
NOT COVERED BY INSPECTION

COMPLAINTS RECEIVED DURING MARCH 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL MODEL 81 SPORTSMAN - 12 GA: SPORTSMAN - 16 GA: SPORTSMAN - 20 GA: MODEL 11 - 12 GA: MODEL 11 - 16 GA:	1948	1947 1 6 5 1 4	1946 10 2 1	1945	MISC. & PARTS
MODEL 11 - 20 GA. MODEL 121 MODEL 141 MODEL 241 MODEL 31 - 12 GA. MODEL 31 - 20 GA. MODEL 31 - 20 GA. MODEL 37	3663-8	8000#3-1-1	25 10 5		
MODEL 510 MODEL 511 MODEL 512 MODEL 513 MODEL 521 MODEL 550 MODEL 550-1	2 1	20 35 6 20	3 1	•	

H.E.WEEKS:FH 4/2/48.

SHEET NO. 6