

Mr. Robert Wessel
130 So. Spring Mill Road
Villanova, Pennsylvania

November 14, 1963

Dear Mr. Wessel:

In order to eliminate the creep in your M/40X trigger a small screw driver should be used to turn in the screw (17053) until approximately .010" engagement is obtained between the connector (16719) and the sear (17946). The screw should then be sealed with DuPont Cement. If this does not remedy the creep, remove the trigger assembly from the rifle and send it to my attention. We will repair it and return to you without charge.

A palm rest could be added to your 40X rifle. The rail and palm rest may be purchased from Roy Dunlap, 2319 Ft. Lowell Road, Tucson, Arizona.

We are enclosing the instruction sheet you requested and an additional descriptive page. If we can be of any further service please feel free to call on us.

Sincerely,

L. F. Gogol, Design Engineer
Ilion Research Division

LPG:nl