

5-3-63
pts.

1. Sears (PM) seem smooth. Top corner
rounded off.

Production Sears sharp top corner. Still have
grind grooves across rear cam surface.