

11-11-6

after 11-10-65 tests

○ Rifle 139413

5 ear can surface that contacts F. Fin. head surface.

Shiny spots showing some wear but not excessive.

5 ear surface that contacts connector surface
Some varnish or rust showing, a black substance like grease piled up where connector c
to a stop.

check at
section varnish or rust.

connector surface shows some varnish or rust

○ Rifle 139555

5 ear can surface - same as above

5 ear surface that contacts connector a large amount
varnish or rust covering most of contact surface

Connector surface shows most of contact area c
with varnish or rust,

* 5 ear can surface were touched during inspection
but other surfaces were not. Fire controls remain
to riders.