

Cust. Complaint.

No GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 002805
 OUTSIDE WORK: SWIVELS AND SCOPE MOUNT- DATE: 2-1-73
 ED. FROM: FULKS SPORTING
 FIRED AMMO TYPE: CLARKSBURG, W.VA.
 & CONDITION: GUN #: 6247427
 PROOP: R.E.P.-A INSP. 73 TEST: 87 CODE: KS = 5/69
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED:
 CHAMBER: O.K. APPROVED:
 TEST: NO APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

CONNECTOR CLEARANCE ON TRIGGER = .0069 (MODEL = 1.076 DRAINING = 1.079)

OF TRIGGER PIN HOLE TO TOP OF TRIGGER = .974 (.973 .971)

COMPLAINT: "FIRES WHEN SAFETY IS MOVED TO FIRE POSITION."

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE MOVEMENT BETWEEN TRIGGER &
 TRIGGER CONNECTOR WILL ALLOW INTERFERENCE
 BETWEEN THE SEAR AND CONNECTOR WHICH PREVENTS
 RETRACTION INTO COCKED POSITION. THE PRESENCE
 OF HARDENED LUBRICANT INCREASES THE POSSIBILITY
 OF A MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3176

AL 0029706