

Model Shop Work Load As of 4-29-74

<u>Work in Process</u>		<u>DATE REQ.</u>	<u>EST Comp.</u>	<u>DAYS BEHIND</u>
<u>1100X</u>	Barrels	5-1	5-3	2
	Frames	—	4-30	—
	Barrel Extension	5-8	5-8	—
	Sear	5-1	4-30	—
	Friction Ring	4-28	4-29	1
	(Test) Bbl. Exten. Ass'y	—	4-29	—
<u>1100</u>	Fore End Supports	5-12	5-11	—
<u>742X</u>	Bolt Heads (ALT.)	4-25	4-29	2
<u>Bullet Job</u>	Bracket + Counter Weight	4-30	4-29	—
<u>3200</u>	Tang Connecting Blocks	5-6	5-7	1
<u>TRAP</u>	Safety Plunger + Housing	4-26	4-29	1

Model Shop Work Load As of 4-29-74

<u>Work on HAND</u>	<u>DATE/REQ.</u>	<u>EST. COMP.</u>	<u>DAYS BEHIND</u>
<u>1100X</u> Feed Latch Spring	6-3	5-16	—
Action Spring	5-2	5-2	—
Trig. Plate Ret. Spring	5-18	5-2	—
Shell Cut off latch Spring	5-15	5-6	—
Port Cover	6-3	5-17	—
Firing Pin	5-23	5-6	—
Trig. Plate Ret. PLUNGER	6-3	5-5	—
Feed Latch	6-3	5-5	—
<u>3200</u> SBT Barrels	5-10	5-14	2
Top Lock Lever Screw	5-2	5-2	—
Bottom Tang (ALT.)	5-1	5-1	—
Slide Block	5-2	5-2	—
Gage Mount	5-3	5-3	—
<u>3200 410ga.</u> Vent Ribs	5-15	5-7	—
Ejector (R+L)	5-15	5-10	—
Front Bbl. Band	5-15	5-13	—
Barrels	5-15	5-15	—
Loop	5-15	5-7	—
Middle Bbl. Band	5-15	5-12	—
<u>1100</u> Slide Block	5-2	5-6	2
<u>1100 20ga L.W.</u> Locking Block	5-6	5-14	5
Barrel Assembly	5-15	5-14	—
<u>742X</u> Trig. Plate Ret. Screw	5-17	5-1	—
<u>Bullet Job</u> Lead Cut-off Fixture	5-2	5-2	—
<u>700</u> Safety (ALT.)	5-30	5-1	—
<u>WONDER II</u> Safety Plunger + Housing	5-2	5-2	—