

OPTIONAL FORM NO. 10
MAY 1962 EDITION
GSA FPMR (41 CFR) 101-11.6

REMINGTON ARMS COMPANY, INC.

STANDARD FORM NO. 64
MAY 1962 EDITION
GSA FPMR (41 CFR) 101-11.6

MANUFACTURERS OF
SPORTING FIREARMS, AMMUNITION

SPORTING FIREARMS, TRAPS, RIFLES, NEW YORK
ALBANY, NEW YORK, BRIDGEPORT, CONNECTICUT
BRIDGEPORT, ARIZONA

TRAPS

TARGETS

PETERS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, BRIDGEPORT, CONNECTICUT
ALMA, CHICAGO, ILLINOIS
ALMA, CHICAGO, ILLINOIS

CABLE - HARTLEY, BRIDGEPORT

BRIDGEPORT, CONNECTICUT 06602

TELE 944-701 STRATFORD, CONN

November 9, 1978

Honsport, Ltd.
1365 Colburn Street
Honolulu, Hawaii - 96817

Gentlemen:

U R G E N T

Attached is a copy of a news release issued to newspapers in Hawaii, relative to the recall of certain Remington guns.

Listed below are the names of the newspapers involved, and the dates on which this news release will appear:

Honolulu Star Bulletin	November 15, 17, 19
Honolulu Star Bulletin and Advertiser	November 19, 26 December 3

Our recent telephone call alerted you to the recall of the Mohawk 600, and Remington Models 600 and 660 for trigger assembly replacements, and you agreed to assist us.

In the very near future, we will provide you with full information on the handling of the repair, and when you may expect shipment of the replacement trigger assemblies.

Special repair forms have been mailed to you with full instructions.

Very truly yours,

E. G. Larson, Manager
Field and Consumer Services

EGG:lb
Attn:

R2506616

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

**Owners of the above guns should contact
one of the following gunsmiths:**

In Anchorage	In Anchorage	In Fairbanks
Howard's Gun Shop	Dill's Gun Shop	Dixon's
528 Fifth Avenue	8729 Lake Otis Parkway	281 College Road
Anchorage, Alaska 99501	Anchorage, Alaska 99507	Fairbanks, Alaska 99701
(907) 272-4570	(907) 349-1312	(907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

**Owners of the above guns should contact
one of the following gunsmiths:**

In Honolulu Honsport, Ltd. 1365 Colburn Street Honolulu, Hawaii 96817 (808) 833-3026 or (808) 949-3591	In Honolulu The Thom Company, Ltd. King & Smith Streets Honolulu, Hawaii 96817 (808) 538-6764	In Honolulu Ka Pu Kapili P.O. Box 745 Honolulu, Hawaii 96727 (808) 773-0244
--	--	--

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.