## DON'T SAY IT - WRITE IT

J. P. LINDE - F. E. MARTIN

Date May 12, 1977

A. A. HUGICK

Two years ago the XP-100 bolt plug and safety assembly designs were reviewed due to pending impact test of exposed hammer — striker assemblies. The safety has been modified with thumb piece material charge — BUT — bolt plug changes have not been implemented. Aduse of the M/600 bolt plug for eliminating an exposed striker should be implemented as soon as possible.

AAH:bd Measurement/Test Lab Ilion Research Division

Copies to: C.B. Workman

File

## DON'T BE SORRY — BE SAFE

CC: C.B. WORKMAN

## DON'T SAY IT - WRITE IT

TO J. P. LINDE - F. E. MARTIN From A. A. HUGLEK Date 5-//-77

TWO YEARS AGO THE XP-100 BOLT PLUL AND SAFETY
ASSEMBLY DESIGNS WERE RELIEWED DUE TO PENDINGIMPACT TEST OF EXPOSED HAMMER - STRIKER ASSEMBLIESO
THE SAFETY HAS BEEN MODIFIED WITH THUMB PIECE
MATERIAL CHANGE - BUT - BOLT PLUG CHANGES HAVE
NOT BEEN IMPLEMENTED. ADUSE OF THE MGOD BOLT
PLUG FOR ELIMINATING AN EXPOSED STRIKER SHOULD
BE IMPLEMENTED AS SOON AS POSSIBLES

DON'T RE SORRY - BE SAFE